

# Freight Forwarders Tanzania Ltd. Dar es Salaam, Tanzania

#### Submitted to:

International Cyanide Management Institute (ICMI) 1400 I Street, NW - Suite 550 Washington, DC 20005 UNITED STATES OF AMERICA Freight Forwarders Tanzania Ltd PO Box 179 Dar es Salaam Tanzania

REPORT



**Report Number.** 14514150069.501/B.1

Distribution:

ICMI - 2 copies (1 pdf)
Freight Forwarders Tanzania Ltd - 1 copy (pdf)
Golder Associates (UK) Ltd - 1 copy





# **Table of Contents**

1.0	SUMMARY AUDIT REPORT FOR TRANSPORTATION1				
2.0	LOCATION DETAIL AND DESCRIPTION OF OPERATION				
		Facility Location			
	2.2	Background	1		
SUM	MARY A	UDIT REPORT	4		
	Auditors	s Findings	4		
	Name of Other Auditors				
	Dates o	f Audit	4		
PRIN	ICIPLE 1	- TRANSPORT	5		
PRIN	NINCIPLE 2 – INTERIM STORAGE9				
DDIA	ICIDI E 3	EMERCENCY RESPONSE	40		



December 2014 Report No. 14514150069.501/B.1



#### 1.0 SUMMARY AUDIT REPORT FOR TRANSPORTATION

Name of Cyanide Transportation Facility: Freight Forwarders Tanzania Ltd

Name of Facility Owner: Freight Forwarders Group

Name of Facility Operator: Freight Forwarders Tanzania Ltd

Name of Responsible Manager: James Redfern, Freight Forwarders Tanzania Ltd

Address: Freight Forwarders Tanzania Ltd

PO Box 179 Dar es Salaam Tanzania

State/Province: Dar es Salaam

Country: Tanzania

 Telephone:
 +255 (0) 22 2139892

 Fax:
 +255 (0) 22 2114969

 E-Mail:
 general@ffwdt.com

## 2.0 LOCATION DETAIL AND DESCRIPTION OF OPERATION

## 2.1 Facility Location

The FFT Mbagala Storage Facility is located off Kilwa Road in the Mbagala industrial area in the south part of Dar es Salaam airport at coordinates 6°54'42.10"S - 39°16'0.61"E. It has an access road and entrance along the eastern boundary and borders the Mainline Carriers Yard on the western boundary. The storage facility contains a dedicated area for the interim storage of cyanide containers; this has only taken place at this location for the last 18 months. At the time of the site visit cyanide containers were being held at this facility.

Golden Coach Ltd (GCL) became a Signatory to the International Cyanide Management Code on 27 May 2014 as part of the repeated requests by companies other than FFT to transport Cyanide to mines not serviced by FFT.

With their sister company, Golden Fleet Ltd (GFL) they have been in operation for over 30 years and are located off Nelson Mandela Road at coordinates 6°50′59.57″S - 39°15′49.21″E in Dar es Salaam. GCL and GFL are separate companies with separate agreements with FFT. However, they operate out of the same location, using the same management team, vehicles and trailers. GFL act as a subcontractor to GCL with regards to the transport of cyanide with GFL providing some of the trucks and drivers. GCL's main client is Freight Forwarders Tanzania Ltd.

# 2.2 Background

FFT became a Signatory to the Code in November 2007 and was certified as being fully compliant with the Code on 22 May 2008 and was recertified in 2011.

FFT coordinates cyanide transportation within Tanzania, and subcontracts the trucking component of transportation to Golden Coach Limited/Golden Fleet Limited (GCL/GFL) and Mainline Carriers Limited (MCL).

Freight Forwarders Tanzania Ltd Name of Facility Oak Hang L

Signature of Lead Auditor

18 December 2014 Date





FFG has been transporting cyanide since 1998 when large scale gold mining started in Tanzania. Initially the transportation was by rail as the roads were of a poor standard. In 2003 the transportation switched to road due to infrastructure improvements and has remained so since that time.

Solid Sodium Cyanide manufactured by Orica Australia Limited (Orica), Australia Gold Reagents (AGR) and Samsung Construction & Trading (SCT) in Korea, is packaged in Intermediate Bulk Containers (IBC), which are in turn packed into a container. The containers contain 17 to 20 1.1 ton IBCs – depending on client requirements and are delivered by ship to the Port of Dar es Salaam, Tanzania. The port is operated by the Tanzania Ports Authority (TPA).

At the Port of Dar es Salaam, the containers are unloaded using dockside container handling equipment by the Tanzania International Container Terminal System (TICTS).

In a cooperative effort between FFT, the Transporters and TICTS, the containers are arranged in a group, away from other dangerous goods while customs and import documents are cleared.

Once documentation is completed (between four and eight days), a convoy assembles and enters the TICTS area for loading. Following a risk assessment, cyanide is loaded at night for transfer to the interim storage yards so that traffic and people are at a minimum.

The convoy comprises a lead vehicle (crew-cab pick-up), the required number of semi-trailer trucks (between 5 and 16), and finally the Cyanide Emergency Spill Response vehicle. Prior to loading, each truck is checked for roadworthiness by the Convoy Leader using a check sheet for guidance. Each driver is also assessed to ensure that his training record is up-to-date, as the there is a requirement for training to be updated on an annual basis.

One container is loaded on each trailer using the TICTS container stacker. During this operation, each container is checked for damage and the seals are noted as being correct and in place. An extra security plate arrangement is placed between the container and the trailer during loading. This security plate arrangement ensures that even if the seals are broken the doors of the container cannot be opened.

Once loaded the convoy of trucks with the escort vehicles departs the TICTS area and the Port. The Convoy travels to one of two vehicle depots, either the GCL vehicle yard or the FFT storage facility.

If a convoy is scheduled to travel directly to the client or if loading takes place overnight or finishes after 15:00, either the GCL yard on Mandela Road or the FFT Yard in Mbagala are used for overnight parking and the drivers go home and rest until the following day. This is as per FFT's and GCL's procedure for overnight storage to avoid travelling in the hours of darkness and is also part of the Fatigue Management Plan. The convoy then departs the yard the following morning.

If the Cyanide is scheduled to be stored for later transport to the client, the FFT Mbagala yard is used as an Interim Storage Facility and the containers are offloaded by a container handler and stacked in a designated area within the yard. The containers will be re-loaded at a later time for transport to the client sites. At that time, the same procedures for driver training, truck roadworthiness and container integrity are used as in the TICTS area.

Convoys usually leave the city of Dar es Salaam for client sites early in the morning, following a pre-convoy toolbox meeting held by the Convoy Leader.

Jak Hong L

Signature of Lead Auditor

18 December 2014



Report No. 14514150069.501/B.1



Convoys only operate during daylight hours, 06:00 and 18:00, to limit driver fatigue and ensure that should there be an incident there is some daylight remaining to effect immediate first response. To minimize stoppages the transporter usually has at least two less critical Non-Cyanide Loads travel with the convoy. In the event of a rig breakdown the rig from one of these loads can be switched with the broken down rig allowing the cyanide containers to continue to the client site with the non-cyanide load remaining to be collected later. Once at a client site, the cyanide containers are offloaded by the client.

Routes to the Client sites have been route risk assessed and the most suitable routes selected. The condition of transport infrastructure from the Port of Dar es Salaam to the mine site locations varies greatly, ranging between high quality sealed roads, sections of tarmac in poor condition to gravel/dirt roads in poor condition.

At the time of the audit, FFT delivered to five client sites within Tanzania and two in Democratic Republic of Congo (DRC). If required they are also able to deliver to North Mara mine; normally serviced by Freight Forwarders Kenya Limited as shown in Table 1.

Currently FFT deliver to five client sites within Tanzania.


Table 1: Mines delivered to by FFT

	Client	Supplier	Distance	Travel Time
1	Shanta Mining - Shanta Mine	SCT	980 Km	3-4 Days
2	Resolute - Golden Pride Mine	AGR	Discontinued in Jan 2014	
3	Barrick - North Mara Mine	Orica	1,450 Km	4-5 Days
4	Barrick - Buzwagi Mine	Orica/SCT	1,030 Km	3-4 Days
5	Barrick - Bulyanhulu Mine	Orica/SCT	1,120 Km	3-4 Days
6	AngloAshanti - Geita Gold Mine	AGR	1,170 Km	3-4 Days
7	Banro - Bukavu for Twangiza	Orica	1,930 Km	9-11 Days
8	Banro - Namoya Mine	Orica	1,980 Km	11-14 Days

Jak Hang L







Report No. 14514150069.501/B.1



# **SUMMARY AUDIT REPORT Auditors Findings**

	<u> </u>		
	⊠ in full comp	liance with	The International
Freight Forwarders Tanzania	Ltd is: ☐ in substantia	I compliance with	Cyanide Management
	not in compli	ance with	
This operation has maintained the previous three-year audit cy		e International Cyanide	Management Code throughou
Audit Company:	Golder Associates		
Audit Team Leader:	Dale Haigh, Lead Aud	itor and Technical Speci	alist
Email:	dhaigh@golder.com		
Name of Other Audit	ors		
Name, Position		Signature	
Ed Perry, ICMI Pre-certified Au	ditor	A	
Dates of Audit The Certification Transport Aud	lit was undertaken withi	n one day (one person-c	day) on 23 September 2014.
I attest that I meet the criteria Team Leader, established by a audit team meet the applicable Code Verification Auditors.	the International Cyanic	de Management Institut	e and that all members of the
I attest that this Summary Audattest that the verification audit Cyanide Management Code Veand accepted practices for heal	was conducted in a properification Protocol for C	ofessional manner in acc Cyanide Transportation (	cordance with the Internationa
Freight Forwarders Tanzania L		tt mg L	18 December 2014
Name of Facility Signature of		Lead Auditor	Date

Freight Forwarders Tanzania Ltd Name of Facility

Signature of Lead Auditor

18 December 2014
Date
Golder
Associates



# **PRINCIPLE 1 – TRANSPORT**

# **Transport Cyanide in a Manner that Minimizes the Potential for Accidents and Releases**

Transport Practice 1.1:	Select cyanide routes to minimize the potential for accidents and releases.				
	$oxed{\boxtimes}$ in full com	pliance with			
The operation is	in substant	ial compliance with	Т	ransport Practice 1.1	
	not in com	oliance with			
Summarise the basis for t	his Finding/De	ficiencies Identified:			
The operation is in full com the potential for accidents a		ansport Practice 1.1; se	elect cyar	nide transport routes to minimiz	
	ential for accide			procedure for the transport rout onment where there are limite	
restrictions and numerous report on conditions during	actions were id each trip. FFT, gencies as nece	entified and implemente its clients and suppliers essary (during the period	ed to imp s have co	2014) and analysed for risks an rove safety. Drivers assess an nsulted various stakeholders and 2014) in the selection of route	
				f the road conditions (traffic an and fitted with warning signs an	
				y support (Police and Hospitals and advised of their roles durin	
Service Level Agreements	require MCL a	nd GCL/GFL to comply	with the	Service Level Agreements. The ICMC. FFT has developed a this has been used through the	
Transport Practice 1.2:		an perform their jobs v		ide handling and transpo imum risk to communities an	
	⊠ in full com	pliance with			
The operation is	in substant	ial compliance with	Т	ransport Practice 1.2	
	not in com	oliance with			
Summarise the basis for t	his Finding/De	ficiencies Identified:			
•	The operation is in full compliance with Transport Practice 1.2; ensure that personnel operating cyanide nandling and transport equipment can perform their jobs with minimum risk to communities and the environment.				

<u>Freight Forwarders Tanzania Ltd</u> Name of Facility Signature of Lead Auditor

18 December 2014 Date





FFT does not own and operate transport trucks directly. FFT does however manage the Mbagala interim storage facility and within this storage facility, FFT only uses trained and competent operators to drive its fork lift trucks within its interim storage yard. FFT sub-contracts the driving of trucks carrying cyanide to GCL/GFL and MCL. Both GCL/GFL and MCL have only used trained and competent operators to drive its trucks (during the period between 2011 and 2014) and the companies maintain files on their drivers that contain copies of licences (heavy vehicle drivers licences) and training records. FFT maintains copies of the files on drivers used by its subcontractors.

There is no requirement in Tanzania for drivers to be licensed for dangerous goods transport. However, all personnel from FFT, MCL and GCL operating cyanide handling and transport equipment have been trained to perform their jobs in a manner that minimises the potential for cyanide releases and exposures. The training of cyanide handling and transport equipment operators is coordinated by FFT. Records show that such training continued during the period 20011 to 2014.

Interviews with drivers at FFT, MCL and GCL/GFL indicated that all FFT and subcontractor personnel operating cyanide handling and transport equipment are competent to perform their jobs in a manner that minimises the potential for cyanide releases and exposures.

FFT subcontracts the transport of cyanide to MCL, GCL and GFL under Service Level Agreements. The Service Level Agreements require MCL and GCL/GFL to comply with the ICMC. FFT has developed an audit protocol to assist in the subcontractor performance assessment and this has been used through the period 2011 to 2014.

Transport Practice 1.3:	Ensure that transport equipment is suitable for the cyanide shipment.		
	oxtimes in full compliance with		
The operation is	in substantial compliance with	Transport Practice 1.3	
	not in compliance with		

#### Summarise the basis for this Finding/Deficiencies Identified:

The operation is in full compliance with Transport Practice 1.3; ensure that transport equipment is suitable for the cyanide shipment.

FFT and its subcontractors MCL and GCL only use equipment designed and maintained to operate with the design loads.

FFT has procedures in place to verify the adequacy of the equipment for the load it must bear and its fitness for purpose. FFT has performed daily vehicle checks during convoys carried out between 2011 and 2014, and these are documented. MCL and GCL subcontractors also have routine maintenance schedules and ad hoc maintenance procedures that include checks for structural problems on the vehicles. These checks were performed during the period 2011 to 2014. Both MCL and GCL/GFL maintain records of vehicle specifications and maintenance history. FFT has performed maintenance checks on the forklift truck which is of sufficient capacity to lift full cyanide containers.

FFT has procedures in place to prevent overloading of the transport vehicles being used for handling cyanide. MCL and GCL/GFL trucks and trailers were purchased to a design specification appropriate for the cyanide transport task.

Both MCL and GCL/GFL have sufficient vehicles for transporting cyanide to ensure that no other vehicles are used. In addition, the load limits of the containers, the axle loadings allowed for the vehicles and the vehicle design specifications ensure that the vehicles will not be overloaded. The procedures and inspections carried out ensure that only one cyanide container is loaded and that no other material is added to the vehicles.

<u>Freight Forwarders Tanzania Ltd</u> Name of Facility Signature of Lead Auditor





<b>Transport Practice 1.4:</b>	Develop and implement a safety program	for transport of cyanide.
The operation is	in substantial compliance with	<b>Transport Practice 1.4</b>
	not in compliance with	
Summarise the basis for t	his Finding/Deficiencies Identified:	
The operation is in full comparing transport of cyanide.	pliance with Transport Practice 1.4; develop a	nd implement a safety program for
transported in a manner that ensuring that containers are	cedures (between 2011 and 2014) which hat maintains the integrity of the packaging by a securely attached to the trailers using twist lins in place during the convoy.	its subcontractors. These include
convoy. These signs are a vehicles carry red flags an	by FFT by its subcontractors to identify shipment tached to the lead vehicles and all cyanide or dipped headlights are used. The signage each day as the convoy progresses.	ontaining vehicles. In addition, the
cyanide containers by FFT's conjunction with its subcont and preventive maintenance convoy leaders who ensure which also monitors driver h	vehicles that were purchased to a design spansion subcontractors. FFT has developed a Safety ractors MCL and GCL. This includes vehicle activities. Limitations on driver hours are also that driver hours are limited each day, and the lours. Procedures have been followed to preving or suspending travel during severe weath propriate action.	y Program which is implemented in inspections prior to each shipment o managed; Locally through use of the GPS system ent loads from shifting. Procedures
FFT and its sub-contractors Safety Program.	s have drug prevention policies. Records are	e maintained for all aspects of the
Transport Practice 1.5:	Follow international standards for transpair.	portation of cyanide by sea and
	☑ in full compliance with	
The operation is	in substantial compliance with	<b>Transport Practice 1.5</b>
	not in compliance with	
Summarise the basis for t	his Finding/Deficiencies Identified:	
The operation does not invo	lve shipment by sea or air and so Transport P	ractice 1.5 does not apply.
Transport Practice 1.6:	Track cyanide shipments to prevent losse	s during transport.
	☑ in full compliance with	
The operation is	in substantial compliance with	Transport Practice 1.6
	not in compliance with	
Summarise the basis for t	his Finding/Deficiencies Identified:	
Freight Forwarders Tanzania Ltd Name of Facility	Signature of Lead Auditor	18 December 2014 Date



The operation is in full compliance with Transport Practice 1.6; track cyanide shipments to prevent losses during transport.

Through its sub-contractors MCL and GCL/GFL, FFT has effective means of communication with their transport vehicles. Communication systems include GPS tracking which is used for all cyanide shipments; the use of satellite and long-range cell phones which are continuously on. All communication equipment is checked during the convoy pre-checks prior to the start of each convoy.

Communication risk areas only relate to small areas where the cell phone may not have a signal, although coverage throughout Tanzania is generally good, but a satellite phone is carried as back up should the signal fail.

FFT has systems to track the progress of cyanide shipments. FFT's subcontractors use a GPS system (which is continuously monitored) to track progress along the routes while FFT log convoy movements using telephone text messaging, which are also recorded. All information is shared between the parties.

FFT has appropriate inventory controls and/or chain of custody documentation to prevent loss of cyanide during shipment. Vehicles are also weighed at weighbridge stations along the route which verifies that no material is lost. All trucks carry a material safety datasheet for sodium cyanide.

Jak Hong L

Signature of Lead Auditor

Golder



#### PRINCIPLE 2 – INTERIM STORAGE

Design, Construct and Operate Cyanide Trans-shipping Depots and Interim Storage Sites to Prevent Releases and Exposures.

Store cyanide in a manner that releases.	minimizes the potential for acc	idental
$oxed{\boxtimes}$ in full compliance with		
☐ in substantial compliance with ☐ not in compliance with	Interim Storage Practice 2.1	
	releases.  in full compliance with in substantial compliance with	<ul> <li>☑ in full compliance with</li> <li>☐ in substantial compliance with</li> <li>☐ Interim Storage Practice 2.1</li> </ul>

#### Summarise the basis for this Finding/Deficiencies Identified:

The operation is in full compliance with Transport Practice 2.1; store cyanide in a manner that minimizes the potential for accidental releases.

The Mbagala interim storage facility is secured to prevent unauthorised access to cyanide, and has appropriate warning signs alerting workers (no smoking, eating and drinking in the cyanide storage area, no naked flames in the cyanide storage area, and PPE requirements). Incompatible materials such as acids and strong oxidisers are stored more than 10 m from the cyanide interim storage area. No explosives are stored at the Mbagala interim storage facility.

Cyanide is stored within the original shipping containers that are designed to minimise the potential for contact of solid cyanide with water.

The shipping containers are not opened while in storage and they are stored outside on an area of hardstanding.

Systems and resources are in place on the site to contain and remediate any spilled cyanide materials and minimise the extent of a release. No incidents have occurred in the last 3 years.

Valettag L



# PRINCIPLE 3 – EMERGENCY RESPONSE Ensure that Process Controls are Protective of the Environment.

Emergency Response Practice 3.1:	Prepare detailed releases.	l emergency	response	plans	for	potential	cyanide
	⊠ in full complia	nce with					
The operation is	in substantial co	ompliance with	Emerg	jency R	espo	nse Practio	e 3.1
	not in complian	ce with					

#### Summarise the basis for this Finding/Deficiencies Identified:

The operation is in full compliance with Transport Practice 3.1; prepare detailed emergency response plans for potential cyanide releases.

FFG have a document entitled Cyanide Procedures that contains all of the details of how to respond in an emergency that involves cyanide.

The Cyanide Procedures document has been adapted by FFG from Orica Australia Limited's (Orica) Emergency Response Guide. The Orica Emergency Response Guide provides guidance in the development of specific site and transport route emergency response plans for the management of incidents involving spillage of sodium cyanide product. The document has been modified by FFG to suit the conditions of East and Central Africa.

The Cyanide Procedures document has been developed to be appropriate for the selected transportation routes and interim storage facility, transport infrastructure, the physical and chemical form of cyanide and the design of the transport vehicle.

The Cyanide Procedures cover specific circumstances where they will be used. The document includes Emergency Response Guides for specific scenarios including:

- RG1 dry sodium cyanide spill inside interim storage facility;
- RG2 dry sodium cyanide spill outside interim storage facility;
- RG3 dry sodium cyanide spill inside a sea container;
- RG4 sea container decontamination;
- RG5 handling wet sodium cyanide;
- RG6 dry sodium cyanide spill to a waterway;
- RG7 decontamination of a spill of solid cyanide into soil; and
- RG8 response to an incident with a fire involving sodium cyanide.

External responders identified in the documents are aware of their role in an emergency.



Signature of Lead Auditor

18 December 2014
Date
Golder



Emergency Response Practice 3.2:	Designate appropriate response resources for emergency response.		and commit	necessary
	$oxed{\boxtimes}$ in full compliance with			
The operation is	in substantial compliance with	Emergency	Response Pra	actice 3.2
	not in compliance with			
Summarise the basis for t	his Finding/Deficiencies Identified:			
•	npliance with Transport Practice 3.2; dources for emergency response.	lesignate app	ropriate respon	ise personnel
provided by the HSE and given to all appropriate pe	ors MCL and GCL/GFL provide the san Training Manager for GCL/GFL and M rsonnel. All drivers transporting cyani- dically by Cyanide Convoy Procedures.	ICL. The eme de receive a	ergency respon	se training is
The Cyanide Procedures do for the following positions:	ocument identifies the key roles and res	sponsibilities ii	n the event of a	ın emergency
Cyanide Code Manage	er			
Cyanide Convoy Lead	er;			
■ Emergency Response	(ER) Truck Driver;			
Convoy Lead Drivers				
Local Authorities.				
Interim Storage Yard S	Supervisor; and			
Interim Storage Yard V	Vorker.			
The requirements are clear	and unambiguous and are also covered	d in the trainin	g programmes.	
available en-route. A list of checked and tested before	quipment is taken in the Emergency Resemergency response equipment is docuevery convoy of vehicles leaves. All drembles that includes essential PPE and	umented on a rivers are issu	checklist. The ued with a 'Get	equipment is Out Alive' kit
Emergency Response Practice 3.3:	Develop procedures for internal an reporting.	nd external e	mergency not	ification and
	in full compliance with			
The operation is	in substantial compliance with	Emergency	Response Pra	actice 3.3
	not in compliance with			
Summarise the basis for t	his Finding/Deficiencies Identified:			
The operation is in full com emergency notification and	pliance with Transport Practice 3.3; dereporting.	velop procedu	ures for internal	and external

December 2014 Report No. 14514150069.501/B.1

Freight Forwarders Tanzania Ltd Name of Facility

18 December 2014 Date



Dakttongh

Signature of Lead Auditor



Systems are in place to ensure that internal and external emergency contact information and reporting procedures are kept current.

The Emergency Call List and Plan Activation sections of the Cyanide Procedures document contain details on how the emergency response procedures are activated including details of who is contacted. This includes emergency personnel, internal personnel, the shipper, the receiver and the regulatory authorities.

A test of the numbers of the internal and external responders is undertaken annually through a Community Awareness road trip and the Cyanide Procedures updated in response to this.

Emergency Response Practice 3.4:	Develop procedures for remedia additional hazards of cyanide treats	ntion of releases that recognize the ment chemicals.
	$oxed{oxed}$ in full compliance with	
The operation is	in substantial compliance with	<b>Emergency Response Practice 3.4</b>
	not in compliance with	
Summarise the basis for t	his Finding/Deficiencies Identified:	
•	impliance with Transport Practice 3.4 additional hazards of cyanide treatmen	; develop procedures for remediation of t chemicals.
Procedures) states that "Finternational Cyanide Mana	FT, FFK & Orica Mining Chemicals sigement Code in that no chemicals are	Spill to a Waterway (part of the Cyanide subscribe to the recommendations of the e to be added to a flowing waterway in the with their own toxicity characteristics."
	a Spill of Solid Cyanide into Soil' (part rite for use where there has been conta	of the Cyanide Procedures) recommends amination of the soil.
Ferrous sulphate and hydro	gen peroxide are not carried by the cor	nvoy as part of their spill kit.
Emergency Response Practice 3.5:	Periodically evaluate response pr	rocedures and capabilities and revise
	$oxed{\boxtimes}$ in full compliance with	
The operation is	in substantial compliance with	Emergency Response Practice 3.5
	not in compliance with	
Summarise the basis for t	his Finding/Deficiencies Identified:	
The operation is in full com and capabilities and revise t		periodically evaluate response procedures
The Cyanide Procedures coare being implemented.	ontains provisions for periodically review	wing and evaluating its adequacy and they
responsible people are req		the Cyanide Procedures states that the annually, and after any of the following
Incidents;		

December 2014 Report No. 14514150069.501/B.1

Freight Forwarders Tanzania Ltd

Name of Facility

18 December 2014 Date



Wate Hough

Signature of Lead Auditor



- Emergencies;
- Emergency exercises; and
- Transportation audits and assessments.

A full scale incident scenario was undertaken on 13 June 2014 jointly between FFT and GCL. The Cyanide Emergency Drill Report for this was observed.

The drill involved a simulated vehicle incident and associated cyanide spill. The drill took place on one truck in a 16 truck convoy. The drill involved Morogoro Regional Police. Following the drill the write up included areas where improvements could be made which included additional training requirements. Since the drill a number of these training requirements have been undertaken and others are planned.

Jak Hang L

Signature of Lead Auditor

Golder



# **Report Signature Page**

**GOLDER ASSOCIATES (UK) LTD** 

)akttong L

Dale Haigh

Lead Auditor/Transportation Technical Specialist

Sophie Wheeler

Project Manager/Reviewer

Saheele.

Date: 18 December 2014

DH/EP/SW/pr

Company Registered in England No.1125149
At Attenborough House, Browns Lane Business Park, Stanton-on-the-Wolds, Nottinghamshire NG12 5BL

VAT No. 209 0084 92

Golder, Golder Associates and the GA globe design are trademarks of Golder Associates Corporation.



At Golder Associates we strive to be the most respected global group of companies specialising in ground engineering and environmental services. Employee owned since our formation in 1960, we have created a unique culture with pride in ownership, resulting in long-term organisational stability. Golder professionals take the time to build an understanding of client needs and of the specific environments in which they operate. We continue to expand our technical capabilities and have experienced steady growth with employees now operating from offices located throughout Africa, Asia, Australasia, Europe, North America and South America.

Africa + 27 11 254 4800 Asia + 852 2562 3658 Australasia + 61 3 8862 3500 Europe + 356 21 42 30 20 North America + 1 800 275 3281 South America + 55 21 3095 9500

solutions@golder.com www.golder.com

Golder Associates (UK) Ltd Cavendish House Bourne End Business Park Cores End Road Bourne End Buckinghamshire SL8 5AS UK

T: [+44] (0) 1628 851851

