

Auditor Credentials Form

Facility Audited: Harmony Kusasalethu (formerly Elandsrand) Gold Plant, South Africa

Date: 18th – 22nd January 2010

Lead Auditor Credentials

Lead Auditor: Arend Hoogervorst
 Eagle Environmental
 Private Bag X06
 KLOOF 3640, South Africa

Tel: - +27 31 7670244
 Fax: - +27 31 7670295
 Email: - arend@eagleenv.co.za

Certifying Organization: Name: RABQSA
 Telephone Number: - +61 2 4728 4600
 Address: P O Box 347, Penrith BC, NSW 2751, Australia
 Web Site Address: - www.rabqsa.com

Auditor Certification Number: 12529

Minimum experience: 3 audits in past 7 years as Lead Auditor

| Year | Type of Facility, Type of Audit Led | Country & State/Province |
|--|---|--|
| 1991 to 2007 – 111 audits (Audit logs held by RABQSA & ICMI) | Chemicals, manufacturing, oil and gas, mining (gold, coal, chrome), foods, and heavy industry sectors. EMS, Compliance, Environmental Due Diligence, HSEC, SHE audits. Lead Auditor in 81 audits. | South Africa, Botswana, Mozambique, Mali, Namibia, Ghana |
| 2006 | ICMI Cyanide Code Compliance Audits: Lead Auditor *Sasol Polymers Cyanide Plants 1 & 2 and Storage Areas (Production) *Sasol SiLog (Transportation) | South Africa South Africa |
| 2007 | ICMI Cyanide Code Compliance Audits: Lead Auditor *AngloGold Ashanti West Gold Plant *AngloGold Ashanti East Gold Acid Float Plant *AngloGold Ashanti Noligwa Gold Plant *AngloGold Ashanti Kopanang Gold Plant *AngloGold Ashanti Savuka Gold Plant *AngloGold Ashanti Mponeng Gold Plant | South Africa South Africa South Africa South Africa South Africa South Africa |
| 2007 | ICMI Cyanide Code Gap Analyses: Lead Auditor *Goldfields Tarkwa Gold Mine *Goldfields Abusso Damang Mine *Goldfields South Deep Gold Mine *Goldfields Beatrix 1 Gold Mine *Goldfields Beatrix 2 Gold Mine *Goldfields Driefontein No 1 Gold Mine | Ghana Ghana South Africa South Africa South Africa |

| | | |
|------|---|--|
| 2008 | <ul style="list-style-type: none"> *Goldfields Kloof No 1 Gold Mine *Goldfields Kloof No 2 Gold Mine *Goldfields Driefontein No 2Gold Mine *Goldfields Driefontein No 3 Gold Mine *Goldfields St Ives Gold Mine *Goldfields Agnew Gold Mine * Harmony No 1 Gold Plant *AngloGold Ashanti Africa – Morila Gold Mine * AngloGold Ashanti Africa – Sadiola & Yatela Gold Mines <p>ICMI Cyanide Code Compliance Audits: Lead Auditor</p> <ul style="list-style-type: none"> *Goldfields Tarkwa Gold Mine *Goldfields Abusso Damang Mine *Vehrad Transport & Haulage * Goldfields South Deep Gold Mine * Goldfields Beatrix Gold Mine *Goldfields Driefontein Gold Mine * Goldfields St Ives Gold Mine * Goldfields Agnew Gold Mine * Goldfields Kloof Gold Mine * AngloGold Ashanti Africa – Siguiri Gold Mine * AngloGold Ashanti Africa – Yatela Gold Mine | <p>South Africa South Africa South Africa South Africa Australia Australia South Africa Mali Mali</p> <p>Ghana Ghana Ghana South Africa South Africa South Africa Australia Australia South Africa Guinea Mali</p> |
| 2008 | <p>ICMI Cyanide Code Gap Analyses: Lead Auditor</p> <ul style="list-style-type: none"> *AngloGold Ashanti Africa – Navachab Gold Mine *AngloGold Ashanti Africa – Gaita Gold Mine *Harmony Doornkop Gold Mine *AngloGold Ashanti Africa – Iduapriem Gold Mine *AngloGold Ashanti Africa – Siguiri Gold Mine *Harmony Central Gold Mine *Harmony Kalgold Gold Mine *Harmony Evander Gold Mine *Harmony Target Gold Mine *Harmony Saaiplaas Gold Mine | <p>South Africa South Africa South Africa South Africa South Africa South Africa South Africa South Africa South Africa</p> |
| 2009 | <p>ICMI Cyanide Code Compliance Audits: Lead Auditor</p> <ul style="list-style-type: none"> *Sasol Polymers Cyanide Plants 1 & 2 and Storage Areas (Production) *Sasol SiLog (Transportation) | <p>South Africa South Africa</p> |

Cyanide-related Operations Experience



Each auditor must have at least 3 years; at least one auditor must have at least 7 years experience

| Auditor | Yrs. | Relevant Position Titles | Types of Operations |
|---------------|------|---|--|
| Dawie Viljoen | 32 | 2009 | ICMI Cyanide Code Compliance Audits: Technical Auditor *Sasol Polymers Cyanide Plants 1 & 2 and Storage Areas (Production) *Sasol SiLog (Transportation) |
| | | 2008 | ICMI Cyanide Code Compliance Audits: Technical Auditor *Goldfields Tarkwa Gold Mine *Goldfields Abusso Damang Mine * Goldfields South Deep Gold Mine * Goldfields Beatrix 2 Gold Mine * Goldfields Beatrix 1 Gold Mine * Goldfields Driefontein 1 Gold Mine * Goldfields Driefontein 2 Gold Mine * Goldfields Driefontein 3 Gold Mine * Goldfields St Ives Gold Mine * Goldfields Agnew Gold Mine * Goldfields Kloof 1 Gold Mine * Goldfields Kloof 2 Gold Mine |
| | 2008 | ICMI Cyanide Code Gap Analyses: Technical Auditor *AngloGold Ashanti Africa – Navachab Gold Mine *AngloGold Ashanti Africa – Gaita Gold Mine *Harmony Doornkop Gold Mine *AngloGold Ashanti Africa – Iduapriem Gold Mine *AngloGold Ashanti Africa – Siguiri Gold Mine *Harmony Central Gold Mine *Harmony Kalgold Gold Mine *Harmony Evander Gold Mine *Harmony Target Gold Mine *Harmony Saaiplaas Gold Mine | |
| | 2007 | ICMI Cyanide Code Compliance Audits: Technical Auditor *AngloGold Ashanti West Gold Plant *AngloGold Ashanti East Gold Acid Float Plant *AngloGold Ashanti Nologwa Gold Plant *AngloGold Ashanti Kopanang Gold Plant *AngloGold Ashanti Savuka Gold Plant *AngloGold Ashanti Mponeng Gold Plant | |

| | | | |
|--|--|--|--|
| | | <p>2007</p> <p>2006</p> <p>2000 to 2007</p> <p>1997 - 2000</p> <p>1995 - 1997</p> <p>1990 - 1995</p> <p>1987 – 1990</p> <p>1980- 1985</p> <p>1977 - 1980</p> | <p>ICMI Cyanide Code Gap Analyses: Technical Auditor</p> <ul style="list-style-type: none"> *Goldfields Tarkwa Gold Mine *Goldfields Abusso Damang Mine *Goldfields South Deep Gold Mine *Goldfields Beatrix 1 Gold Mine *Goldfields Beatrix 2 Gold Mine *Goldfields Driefontein No 1 Gold Mine *Goldfields Kloof No 1 Gold Mine *Goldfields Kloof No 2 Gold Mine *Goldfields Driefontein No 2 Gold Mine *Goldfields Driefontein No 3 Gold Mine *Goldfields St Ives Gold Mine *Goldfields Agnew Gold Mine * Harmony No 1 Gold Plant *AngloGold Ashanti Africa – Morila Gold Mine * AngloGold Ashanti Africa – Sadiola & Yatela Gold Mines <ul style="list-style-type: none"> *AngloGold Ashanti West Gold Plant *AngloGold Ashanti East Gold Acid Float Plant *AngloGold Ashanti Nologwa Gold Plant *AngloGold Ashanti Kopanang Gold Plant *AngloGold Ashanti Savuka Gold Plant *AngloGold Ashanti Mponeng Gold Plant <p>Managing Member Afritech Technical and Management services</p> <p>Manager: AngloGold Ashanti Metallurgical Technical Services</p> <p>Metallurgical Manager: Vaal Reefs Exploration and Mining Company</p> <p>Project Metallurgist: Vaal Reefs Exploration and Mining Company Projects</p> <p>Plant Manager: Vaal Reef Exploration and Mining Company</p> <p>Production Superintendent Anglo American</p> <p>Snr Plant Metallurgist – Anglo American</p> |
|--|--|--|--|

Statement of No Conflict

I certify that I have not audited any component of this facility for which I was responsible for design or development; nor have I within the past year been an employee of the facility, its parent company, or associated affiliates. Excluding audits, I have not derived more than 30% of my income within the past 5 years from the facility, its parent, or associated affiliates. I have not participated in more than two consecutive Cyanide Code audits of this facility. I have participated in at least 3 health, safety, and/or environmental audits in the past 7 years and am familiar with standard audit procedures as well as with the protocols developed by the International Cyanide Management Institute for implementation of the Code.

| Signed, | Name | Signature | Date |
|---------------------|-------------------|---|-----------|
| Lead Auditor* | Arend Hoogervorst |  | 9/4/10 |
| Notarised/certified | |  | 9/4/2010 |
| Technical Auditor | Dawie Viljoen | | 16/4/2010 |

*The lead auditor's signature must be certified by notarization or equivalent

ANGELA LOUISE KLYNHANS
Manager Unit Trust Division
Ewing Trust Company
Commissioner of Oaths RSA
28 Old Main Road, Hillcrest, 3610
REF: 9/1/8/2 Hillcrest 07/07/2009