

INTERNATIONAL CYANIDE MANAGEMENT CODE

Auditor Credentials Form

Facility Audited: Kinross Gold Corporation Tasiast Gold Mine, Mauritania

Date: 15 to 19 May 2023

Auditor: Marie Schlechter

Auditor Certification Number: 0136947

Certifying Organization: Institute of Environmental Management and Assessment (IEMA)

Telephone Number: +44 (0) 1522 540069

Address: City Office Park, Tritton Road, Lincoln, LN6 7AS, UK

Website Address: www.iema.net

Years	Types of Facility, Type of Audit	Types of Operations
2023	ICMI Cyanide Code Recertification Audit: Lead and Technical Auditor	Kinross Gold Corporation Tasiast Gold Mine, Mauritania
2022	ICMI Cyanide Code Recertification Audit: Lead and Technical Auditor	AngloGold Ashanti Geita Gold Mine, Tanzania
		Gold Fields, Tarkwa Gold Mine, Ghana
	ICMI Cyanide Code Recertification Audit: Technical Auditor	AngloGold Ashanti, Iduapriem Gold Mine, Ghana
2021	ICMI Cyanide Code Recertification Audit: Lead and Technical Auditor	Newmont, Ahafo Gold Mine, Ghana
		Newmont, Akyem Gold Mine, Ghana
		Gold Fields, Damang Gold Mine, Ghana
	ICMI Cyanide Code Recertification Audit: Technical Auditor	Agnico Eagle Kittilä Gold Mine, Finland
		Barrick, Buzwagi Gold Mine, Tanzania
Cyanide Code Gap Audit, Lead and Technical Auditor	AngloGold Ashanti, Geita Gold Mine, Tanzania	

ICMI CYANIDE CERTIFICATION AUDIT – AUDITOR CREDENTIALS

Years	Types of Facility, Type of Audit	Types of Operations
2020	ICMI Cyanide Code Certification Audit: Technical Auditor	Asanko Gold Mine, Ghana
2019	ICMI Cyanide Code Recertification Audit: Technical Auditor	Barrick, North Mara Gold Mine, Tanzania
	Cyanide Code Gap Audit, Technical Auditor	Harmony Gold Mining Company, One Gold Mine, South Africa
2018	ICMI Cyanide Code Recertification Audits: Technical Auditor	Acacia Mining Plc., Bulyanhulu Gold Mine, Tanzania Gold Fields, South Deep Gold Mine, South Africa Newmont, Ahafo Gold Mine, Ghana Gold Fields, Tarkwa Gold Mine, Ghana
	Cyanide Code Gap Audit, Technical Auditor	Harmony Gold Mining Company, Joel Gold Mine, South Africa Gold Fields, Tarkwa Gold Mine and Ahafo Gold Mine, Ghana
2017	ICMI Cyanide Code Recertification Audits: Technical Auditor	Harmony Gold Mining Company, Target Gold Mine Harmony Gold Mining Company, No.1 Gold Plant Harmony Gold Mining Company, Kusasalethu Gold Mine Harmony Gold Mining Company, Doornkop Gold Mine Harmony Gold Mining Company, Central Gold Mine
2016	Cyanide Code Gap Audit, Technical Auditor	Newmont, Ahafo Gold Mine, Ghana
	ICMI Cyanide Code Recertification Audits: Technical Auditor	Evander Gold Mine, South Africa
2015	ICMI Cyanide Code Recertification Audits: Technical Auditor	AngloGold Ashanti Sadiola Gold Mine, Mali AngloGold Ashanti Yatela Gold Mine, Mali AngloGold Ashanti Siguiri Gold Plant, Guinea
2014	ICMI Cyanide Code Recertification Audits: Technical Auditor	Goldfields South Deep Gold Mine, South Africa
2013	ICMI Cyanide Code Recertification Audits: Technical Auditor	AngloGold Ashanti Kopanang Gold Plant, South Africa AngloGold Ashanti Nologwa Gold Plant, South Africa AngloGold Ashanti West Gold Plant, South Africa

ICMI CYANIDE CERTIFICATION AUDIT – AUDITOR CREDENTIALS

Years	Types of Facility, Type of Audit	Types of Operations
		AngloGold Ashanti Savuka Gold Plant, South Africa AngloGold Ashanti Mponeng Gold Plant, South Africa


Years	Type of Facility, Type of Audit Led	Country
2020	Lead Auditor for a Phase 1 Environmental Site Assessment for a Paint Manufacturing Company	South Africa
2019 and 2020	Lead Auditor for Annual Private Environmental Compliance Audit against regulatory requirements for a LNG Project.	Mozambique
2019	Lead Auditor for a Regulation 34 External Environmental Compliance Audit for a Smelter	South Africa
2018	Lead Auditor for a Private Environmental Compliance Audit against regulatory requirements pertaining to a Floating Powership.	Mozambique
2017	Lead Auditor for an Environmental Management Programme Report commitments and Environmental Authorisation conditions Compliance Audit at a Chrome Smelter	South Africa
2017	Lead Auditor for an Energy Management System at a pipeline company that transports bulk hydrocarbon products.	South Africa
2017	Lead Auditor for an Environmental Management Programme Report commitments and Environmental Authorisation Compliance Audit for a Coal Mine	South Africa

Years	Relevant Position Titles	Types of Operations
2011 - present	Snr Environmental Scientist – Golder Associates	Marie has worked in the gold mining industry since 2000 and gained extensive experience in the management of the industry specific risks associated with the processes and associate infrastructure on gold mines and specifically the cyanidation facilities and associated aspects.
2006 - 2011	Snr Environmental Coordinator – AngloGold Ashanti	


ICMI CYANIDE CERTIFICATION AUDIT – AUDITOR CREDENTIALS

Statement of No Conflict

I certify that I have not audited any component of this facility for which I was responsible for design or development; nor have I within the past year been an employee of the facility, its parent company, or associated affiliates. Excluding audits, I have not derived more than 30% of my income within the past 5 years from the facility, its parent, or associated affiliates. I have participated in at least 3 health, safety, and/or environmental audits in the past 7 years and am familiar with standard audit procedures as well as with the protocols developed by the International Cyanide Management Institute for implementation of the Code.


Signed	Name	Signature	Date
Lead and Mining Technical Auditor	Marié Schlechter		24 October 2023

I certify that this document is a true and correct copy of the original which was reviewed and approved by me. I further certify that from my observation and knowledge no change was made to the original document.

 Date: 24 Oct 2023

COMMISSION OF DATAS
Magistrate Gerhard Kasse
Technical Manager
Building 1, Wapiti Office Park Waterfall City, Midrand

ICMI CYANIDE CERTIFICATION AUDIT – AUDITOR CREDENTIALS

Signed	Name	Signature	Date
Auditor	Benjamin Asiedu		24 October 2023