

Prepared for:

Barrick Cortez HC66 Box 1250 Crescent Valley Nevada USA 89821-1250 INTERNATIONAL CYANIDE
MANAGEMENT CODE
GOLD MINING OPERATION
RECERTIFICATION AUDIT

Summary Report

**Barrick Cortez Mine** 

June 9, 2017

#### TABLE OF CONTENTS

1.	Introduction, Summary, and Attestation	2
2.	Location and description of mining and milling operation	4
3.	Summary Audit Report	7
	Principle 1 – Production	7
	Principle 2 - Transportation	8
	Principle 3 – Handling and Storage	9
	Principle 4 - Operations	10
	Principle 5 – Decommissioning	17
	Principle 6 – Worker Safety	18
	Principle 7 – Emergency Response	21
	Principle 8 – Training	24
	Principle 9 – Dialogue	26

Barrick Cortez
Name of Facility

Signature Lead Auditor

June 9, 2107

Date

### 1. INTRODUCTION, SUMMARY, AND ATTESTATION

This summary report has been prepared to meet the requirements and intentions of the International Cyanide Management Institute (ICMI) to demonstrate that following named project has met the obligations in implementing the International Cyanide Management Code (Code).

Name of Project:		-	Barrick	Cortez		
<b>Project Owner / Operator:</b>			Barrick	Gold		
Name of Responsible Manag	er:		Matthey	w Gili, Ge	neral Ma	nnager
Address and Contact Inform	ation:		<i>Crescer</i> Phone:	Cortez, H nt Valley I (775) 468 (775) 468	Nevada U 3-4400	ox 1250 USA 89821-1250
Audit Company: Audit Team:			Environ	nmental R	esources	Management (ERM)
Lead Auditor:				e Gillen, ( michelle.		erm.com
Gold Mining Technical Expert	Auditor:		•	dorowick udy.fedor		
Date of Audit: This red Auditors Findings:	certificat	ion audit	was co	nducted D	<b>)</b> ecembei	r 12-15, 2016.
	$\boxtimes$	in full c	omplia	nce with		
Barrick Cortez Mine is		in substa	antial co	ompliance	with	International Cyanide Management Code
		not in co	omplian	ce with		
This operation has not experience	ced com	nliance p	roblems	during p	evious tl	hree-vear audit cycle.

Barrick Cortez /W/whell Steller June 9, 2107
Name of Facility Signature Lead Auditor Date

Page 2 of 28

#### **Attestation:**

I attest that I meet the criteria for knowledge, experience and conflict of interest for Code Verification Audit Team Leader, established by the International Cyanide Management Institute and that all members of the audit team meet the applicable criteria established by the International Cyanide Management Institute for Code Verification Auditors.

I attest that this Summary Audit Report accurately describes the findings of the verification audit. I further attest that the verification audit was conducted in a professional manner in accordance with the International Cyanide Management Code Verification Protocol for Gold Mine Operations and using standard and accepted practices for health, safety and environmental audits.

Michelle Gillen	Whilelb Silen	June 9, 2017
Name of Auditor	Signature of Lead Auditor	Date
Name and Signature of O	4 -4	
Judy Fedorowick	furty fishioaciól	June 9, 2017
Name of Auditor	Signature Auditor	Date

Barrick Cortez

Multiple Giller

Name of Facility

Signature Lead Auditor

Date

Page 3 of 28

#### 2. LOCATION AND DESCRIPTION OF MINING AND MILLING OPERATION

The Barrick Cortez (Cortez) gold mine is located 78 kilometers southwest of Elko, Lander County, Nevada and approximately 30 air-miles southeast of Battle Mountain, Nevada. More specifically, the mine is within Sections 28, 29, 30, 31, 32, and 33, Township 28 North, Range 47 East, and Sections 4, 5, and 6, Township 27 North, Range 47 East, Mount Diablo Baseline and Meridian. The Cortez Pipeline property is 11 kilometers northwest and the Cortez Pediment property (which includes the Cortez Hills deposit) is 4 kilometers southeast of the original Cortez milling complex. The Pipeline and South Pipeline deposits are mined by conventional open-pit methods. The Cortez property covers approximately 2,800 square kilometers on one of the world's most highly prospective mineral trends. In 2016 Cortez purchased the Robertson Mine which is located 4 mile north of the Pipeline Mill. The intent is to develop a shallow open pit property with production to commence 2022 to approximately 2029

Cortez employs three different metallurgical processes to recover gold. Lower-grade oxide ore is heap leached, while higher-grade non-refractory ore is treated in a conventional mill using cyanidation and a carbon-in-leach ("CIL") process. In addition, minor amounts of refractory ore is stockpiled and transported off-site for processing. Heap leached ore is hauled directly to leach pads for gold recovery. Carbonaceous mill ore is mined intermittently during the mining of the Pipeline/South Pipeline deposits. The Cortez Hills underground mine is accessed by twin declines portaled in the old Cortez Gold F canyon pit. The breccia ore zone employs underhand cut and fill mining methods with cemented rock fill as backfill. The top cut of the underground mine will eventually be the bottom bench of the Cortez Hills open pit. In the first eleven months of 2016 (up to November 28, 2016), the mine produced 938,761 ounces of gold. Typical amounts in 2015 and 2014 were 1.0 million ounces of gold per annum.

The Cortez Mine's ore bodies extend beneath the pre-mining water tables. Therefore, dewatering of the host rock and alluvium must be performed in advance of mining. The pit is currently dewatered at rates of approximately 22,000 to 27,000 gallons per minute (gpm), with a peak permitted rate of 34,500 gpm, by a system of ten deep bedrock wells, and seven alluvium wells, with an average cased depth of 1818 feet and 904 feet, respectively. The Cortez pit/UG is currently dewatered at rates of 9.000 to 12,000 gpm, by a system of 25 pumping wells in a variety of hydrogeological formations of varying depths. As a whole, Cortez dewatering has a peak permitted pumping rate of 36,100 gpm. The wells discharge to a collection pipeline systems that connect to the Pipeline Infiltration Project infiltration-sites where water percolates into unsaturated alluvium subject to Water Pollution Control Permits. Water quality monitoring has confirmed that the dewatering circuit is separate and distinct from the cyanide processing circuit.

Area 28 facilities consist of a CIC facility, pregnant solution pond, reclaim/barren solution pond, a storm water event pond, and out of service ancillary support facilities to process heap solutions. The Area 28 heap leach facilities have been constructed in association with the tailings impoundment and provide the embankments for the impoundment. The Area 28 tailings impoundment consists of rotating spigot discharge locations and a decant pond area. Cortez uses a ferrous sulfate cyanide detoxification treatment system to keep the spigot discharge below 50 milligrams per liter WAD cyanide. The Area 28 heap leach and tailings facilities are managed as a single process water unit with the decant water pipeline from the tailings decant pond reporting back to Mill #2 for reuse. In addition, the tailings internal underdrain system collects and manages solution from the consolidating tailings and reports to the heap leach process ponds which report back to Mill #2. Area 30 facilities consist of an additional heap leach facility, two pregnant ponds, a barren pond, a storm water event pond, and a CIC recovery facility.

Barrick Cortez

Name of Facility

Signature Lead Auditor

June 9, 2107

Date

Page 4 of 28

All the heap leach and tailings facilities have been constructed with composite HDPE geomembrane and compacted low permeability soil liners. The process water ponds all are constructed with double HDPE geomembrane liners and leak collection and recovery systems. The Mill #2 facility employs a CIL process, storage tanks, thickeners, refinery, mercury scrubber, secondary containment systems, associated appurtenances, and all sumps, pumps and piping necessary to interconnect the components. The Mill #2 facility also includes the Plant Spill Pond (PSP) for spill control. Loaded carbon from the two CIC units is hauled to the Mill #2 facilities for processing. Although the bulk of the processing is done on-site, a relatively small amount of carbonaceous ore is shipped off-site for processing at Barrick's Goldstrike Mine. The operations are designed, permitted and operated as zero-discharge facilities. Approximately 1250 workers are employed at the Cortez mine.

Cortez has four cyanide unloading and storage tank areas: (1) Mill Building; (2) Area 28 Leach; and (3) Area 30 Leach and (4) Area 34 Leach which was constructed in 2012. The Mill cyanide storage tank is 15 feet in diameter and 20 feet high; the Area 28 cyanide tank is 12 feet diameter by 20 feet high (out of service); and Area 30 has two cyanide storage tanks each 12 feet by 20 feet and Area 34 has two cyanide storage tanks each 13 feet by 20 feet. The unloading and storage areas are located away from public access and no surface water bodies are nearby. The storage tank areas and the cyanide unload areas are designed and constructed to contain and recover any leakage from the tanks and the tanker trucks.

Cortez receives liquid sodium cyanide in specially engineered tanker trucks from Cyanco located in Winnemucca, Nevada. Sodium cyanide is delivered by TransWood. Both Cyanco and TransWood are signatories to the Code and have been certified as compliant with the Code by third-party auditors.

Cortez stores and manages sodium cyanide in engineered tanks, pipelines and lined ponds that have had appropriate quality control and quality assurance. Cortez workers are trained in cyanide hazards and first aid, first response, emergency response, and specific operational task training. Cortez facilities are fenced to preclude wildlife and livestock from entering cyanide process areas. Cortez conducts daily, weekly, and monthly inspections to ensure that facilities are functioning as designed and to monitor process solutions. Preventive maintenance programs are in place to assure the continuous operations. Cortez has approved closure and reclamation plans along with financial assurance to complete the appropriate management of cyanide solutions and solids, and the decontamination of cyanide pipelines and equipment.

Cortez has a comprehensive environmental monitoring program to evaluate the performance of the ore processing facilities and containments. The monitoring program includes daily monitoring of pond leak collection systems, quarterly sampling and analysis of groundwater and surface water, and quarterly sampling and analysis of tailings supernatant ponds. Wildlife monitoring is conducted per shift by the operators during facility inspections.

Cortez has an emergency response team that is trained to respond to on-site fires, chemical spills, and worker exposures to cyanide. Cortez works with local community emergency services to assure that adequate resources are available to address both off-site and on-site emergencies.

Upgrades to Cortez's cyanide management facilities since the 2013 recertification include:

- Automated titration systems trailed and fully commissioned at the Mill in 2016; with trial runs at Leach Area 34 underway at the time of re-certifications
- Updated cyanide addition point in CIL Tank #1 so that its bottom added to enhance a faster mixing process.

Barrick Cortez

Name of Facility

Signature Lead Auditor

June 9, 2107

Date

Page 5 of 28

- Lime line to the Ball Mill such to allow cyanide addition at this location
- Commencement of refurbishing of the 20 year old carbon in leach tanks. Tanks #6 and #8 completed in 2016 with the remaining six tanks to be completed by 2020
- CIC tanks refurbished and re-coated in October 2015
- Expansion of the Phase 4 leach pad
- Completion of the Phase II dam raise and initiation of Phase III raise.

The Cortez operation was found to be in Full Compliance with the International Cyanide Management Code; and this operation has not experienced compliance problems during the previous three-year audit cycle.

Barrick Cortez /h/hhelb Steller June 9, 2107
Name of Facility Signature Lead Auditor Date

Page 6 of 28

#### 3. SUMMARY AUDIT REPORT

#### **PRINCIPLE 1 - PRODUCTION**

Encourage responsible cyanide manufacturing by purchasing from manufacturers who operate in a safe and environmentally protective manner.

Standard of Practice 1.1:		Purchase cyanide from manufacturers employing appropriate practices and procedures to limit exposure of their workforce to cyanide, and to prevent releases of cyanide to the environment.		
		in full compliance with		
The operation is		in substantial compliance with	Standard of Practice 1.1	
		not in compliance with		

#### **Basis for Audit Finding:**

Cyanco, located in Winnemucca, Nevada, has been the cyanide producer and supplier for Cortez for the term of the 2016 Recertification Audit – 2013 through 2016. The contract between Barrick Gold of North America (Barrick), which includes the Cortez operation by reference, and Cyanco was signed in May 2008 and became effective January 1, 2009. The term of the contract was extended in July 2011 to be valid through to March 31 2019. The extension letter states all other terms and conditions in the original contract dated May28 2008 shall be incorporated... The contract states that Cyanco shall comply with ICMC's "Principles and Standards of Practice" during the manufacture, transportation, storage, use, and disposal of the product (cyanide) and the supplier shall only deliver product (cyanide) produced in an ICMI Code certified facility.

Cyanco's Winnemucca Production Plant is a Code certified operation as reported on the ICMI website: originally certified October 3, 2006, recertified in 2010 (recertification audit conducted August 10-12, and 14, 2009), and recertified a second time July 12, 2013 (recertification audit conducted January 14-16, 2013). This facility was recertified again November 22, 2016.

Barrick Cortez /h/hhelb Lille June 9, 2107
Name of Facility Signature Lead Auditor Date

Page 7 of 28

### PRINCIPLE 2 – TRANSPORTATION

Protect communities and the environment during cyanide transport.

Standard of Practice 2.1:	I	Establish clear lines of responsibility prevention, training and emergency rwith producers, distributors and trans	esponse in written agreements
	$\boxtimes$	in full compliance with	
The operation is		in substantial compliance with	Standard of Practice 2.1
		not in compliance with	
<b>Basis for Audit Finding:</b>			
-	-	certified as compliant by the IMCI on on July 12, 2013 and again on Novem	
TransWood is a signatory 11, 2006, recertified in 20	to the 0	nly transporter of cyanide from their p Code and Code certified TransWood v ertified July 12, 2013, and the ICMI w January 12, 2017 and is considered a	vas originally certified in October rebsite shows that the TransWood
Standard of Practice 2.2:	1	Require that cyanide transporters impresponse plans and capabilities for cyanide management.	
	$\boxtimes$	in full compliance with	
The operation is		in substantial compliance with	Standard of Practice 2.2
		not in compliance with	
<b>Basis for Audit Finding:</b>			
of Practice" of the Interna storage, use and disposal of transporter to conform to Cyanide Transportation V	tional C of Produ specific erificat	Cyanco requires Cyanco to comply we Cyanide Management Code during the uct (cyanide). Compliance with the Code compliance matters set out in the Code ion Protocols. These Verification Protocotes, unloading and other requirement	manufacture, transportation, ode requires that the supplier and de's Cyanide Production and ocols specifically address packing,
agreement(s) with Subcon	tractor(	ntract requires that Cyanco, the Seller, (s) that clearly designate specific response in transporting and	onsibilities for safety, security,
Barrick Cortez		Whitell Siller	June 9, 2107

Page 8 of 28

Date

Signature Lead Auditor

Name of Facility

The cyanide supply contract between Barrick and Cyanco specifies that Barrick takes ownership of the product at the time the liquid cyanide is delivered into the cyanide storage tank at the mine site. Cortez has Bills of Lading showing that Cyanco and TransWood are the sole suppliers and transporters of the cyanide.

### PRINCIPLE 3 - HANDLING AND STORAGE

Protect workers and the environment during cyanide handling and storage.

Standard of Practice 3.1:		Design and construct unloading, sto consistent with sound, accepted eng control/quality assurance procedure containment measures.	ineering practices, quality
	$\boxtimes$	in full compliance with	
The operation is		in substantial compliance with	Standard of Practice 3.1
		not in compliance with	

#### **Basis for Audit Finding**

Cortez has four cyanide unloading and storage tank areas: Mill Building (Mill); Heap Leach Area 28 (Area 28); Heap Leach Area 30 (Area 30); and Heap Leach Area 34 (Area 34). Area 34 is a new facility since the 2010 Recertification Audit. At the time of the 2016 Recertification Audit, Area 28 remains inactive and the cyanide storage tank had been rinsed and left idled.

Cyanide storage tanks include one 26,400 gallon tank at the Mill; two 15,000 gallon tanks at Area 30; one 18,000 gallon tank at Area 28, and two 20,000 gallon tanks at Area 34. The Mill cyanide storage area concrete containment is measured at less than 110 percent; however, the tank is maintained at the 96 percent level that provides assurance there is 110 percent storage capacity in the secondary containment. The Area 28, Area 30, and Area 34 cyanide storage tank containment areas drain to adjacent barren ponds and are therefore sized appropriately for 110 percent containment.

The facilities for the unload and storage of cyanide have been designed and constructed in accordance with sound and acceptable engineering practices. The design and construction of the cyanide unload and storage facilities including piping have been completed appropriately as documented in final design and construction drawings prepared and stamped by a licensed engineer. The drawings include concrete and reinforcing layout, concrete elevations and section, steel fabrication details, liquid cyanide storage fabrication details, equipment and piping layout and elevations, piping details, and cyanide supply piping to barren strip area and are maintained on site.

Cyanide storage tanks have level indicators and high level alarms that prevent overfilling.

Cyanide storage tanks are located on concrete pads and within concrete curbed containment that prevent

Barrick CortezMultiple GillerJune 9, 2107Name of FacilitySignature Lead AuditorDate

Page 9 of 28

seepage to the subsurface. Cortez has an inspection and preventative maintenance program for identification and patching of cracks. Inspection records and repair work were reviewed and found to be in order. A recent inspection identified some cracking of the concrete and the repair work was completed once the weather permitted.

The four cyanide unloading and storage tank areas (at the Mill, Area 28, Area 30, and Area 34) are located away from public access and no surface water bodies are nearby.

Standard of Practice 3.2:	1	Operate unloading, storage and mixing facilities using inspections, preventive maintenance and contingency plans to prevent or contain releases and control and respond to worker exposures.				
	$\boxtimes$	in full compliance with				
The operation is		in substantial compliance with	Standard of Practice 3.2			
		not in compliance with				
Basis for Audit Finding:						
cyanide unloading. The	proced odium C	er have developed SOPs to preventures cover the responsibilities for Cyanide Delivery" SOP includes detained in the source of th	the transporter and the Cortez			
room (or use of a designate checking the beginning ta	ed pers	ares describes requirements for video son when the video system is not workls, referencing the MSDS, and conductivements for PPE are also listed in the	king), continual radio contact, cting a field level risk assessment			
-	-	ide in tank trucks, and therefore waste here are no mixing facilities on-site.	e management of used packaging or			
PRINCIPLE 4 – OPER	ATIO	NS				
Manage cyanide prenvironment.	cocess	solutions and waste streams to p	rotect human health and the			
Standard of Practice 4.1:	Ì	Implement management and operation human health and the environment t inspection and preventive maintenan	utilizing contingency planning and			
	$\boxtimes$	in full compliance with				
The operation is		in substantial compliance with	Standard of Practice 4.1			
Barrick Cortez		Wichell Stoller	June 9, 2107			
Name of Facility		Signature Lead Auditor	Date			

Page 10 of 28

		not in compliance with	
Basis for Audit Finding:			
procedures and responsible maintenance requirements facilities including detail	oilities Plans for the	SOPs and Operating Plans (described for compliance with the Code, included and SOPs cover the safe operation the specific task operating procedure open and computer screens and have	cluding inspection and preventive of the entire cyanide management es. The training manuals are very
ensure changes that poter assessed, managed, and	ntial im approp	ange (MOC) Procedure. The procedure pact to safety, health, and environmentately communicated to all affects approved change is communicated	nent or productivity are identified, ted personnel. Prior to a change
facilities and are sufficient Cortez utilizes a compute and tracking the complet future activities for regular completion. The preventive	to assure the assure the assure to assure the assure to assure the ass	daily shift and weekly basis. These are and document that they are function system (Oracle®) for identifying, at the preventive maintenance activition tive maintenance and includes informatenance program includes all elements, cyanide pumps, back-up generacks and others).	oning within the design parameters. ssigning responsibility, scheduling, es. The Oracle® system identifies nation on the task requirements and nts necessary for cyanide safety at
Nevada WPCP NEV93109 Operating strategies to c	and Nover no	and tailings management plans in co EV 2007106 that were updated as pa ormal, emergency and upset operat is are incorporated in the permits and	art of the June 2016 permit renewal. ing conditions for the heap leach
Area 28, and Area 34. O critical components to be at the Mill Building. Area and maintained as require	perating maintai 34 has d. The	erators to operate critical functions g plans have been developed that i ned during power outages. Three 1.6 three 2500 KW standby generators preventative maintenance schedule a system and include annual oil changes	nclude specific instructions on the 5 MW diesel generators are located. The generators are tested monthly and requirements for the generators
Standard of Practice 4.2:		ntroduce management and operating tereby limiting concentrations of cyliniting concentrations of cylines.	•
		in full compliance with	
The operation is		in substantial compliance with	Standard of Practice 4.2
		not in compliance with	
<b>Basis for Audit Finding:</b>			
Barrick Cortez		Michell Stiller	June 9, 2107
Name of Facility		Signature Lead Auditor	Date

Page 11 of 28

Since 2013 Cortez has updated the Mill with automatic titration. This has been in "trial phase" since the beginning of 2015, and was recently initiated at Area 30. Therefore Cortez continues manual titration until such time that full switch to automatic titration is approved. Cortez evaluates cyanide consumption rates, process flow density, pH and solid percentage through the CIL circuit every 4 hours during operation. Cyanide is added in the grind surge tank at a specific target rate to achieve a sodium cyanide value of less than 0.15 pounds NaCN per ton of solution at the tailings outflow from CIL tank #8 (the last tank in the circuit). Differing ore types are evaluated prior to processing, usually at least one year ahead of processing to assess consumption rates. The mill is notified by the Geology Department of upcoming host rock changes to initiate grind recovery and cyanide consumption tests. These tests are column leach tests and 48-hour bottle rolls, where cyanide consumption in pounds per ton (lbs/ton) is calculated along with grind time and size. Cortez targets a cyanide concentration rate of 0.3 to 0.5 pounds per ton ore (lbs/ton) sodium cyanide in the grind surge tank. The daily target fluctuates depending on the actual consumption rate as determined by measurements from the CIL tank #8.

Standard of Practice 4.3:		Implement a comprehensive water magainst unintentional releases.	anagement program to protect
	$\boxtimes$	in full compliance with	
The operation is		in substantial compliance with	Standard of Practice 4.3
		not in compliance with	

### **Basis for Audit Finding:**

Cortez has developed a comprehensive water balance for the Plant Site including the Pipeline Tailings Impoundment, Area 28, Area 30 and Area 34 Heap Leach facilities and associated pond network (prepared by RTW, September 2007). The water balances studies are probabilistic models calibrated to actual site conditions and set up to evaluate "what if" scenarios including probabilistic analysis of the precipitation and ore moisture content. 2007The original model was developed in 2015 for the TSF/area 28 with separate models for the heap leach facilities. This was combined into a single model for the entire site in 2016 (Golder Associates).

The Cortez inspection and monitoring programs require daily measurement of water levels in the process ponds. The Area 28 and 34 operations consist of two solution ponds designed with a 2 foot freeboard. Pond solution levels are monitored daily by operating personnel to ensure the pond levels do not exceed specified freeboard limits. Additionally, the solution level is tracked through a telemetry system monitored in the control room at the Mill. Area 30 has three process ponds that are monitored by telemetry at the Mill. In addition, Cortez presents piezometer data for the Tailings Storage Facility in quarterly reports to NDEP. The water balances are updated on an 'as needed basis' to support tracking and evaluation of the system to prevent overtopping and discharge.

The Cortez tailings and heap leach facilities are designed and operated with adequate freeboard above the operating levels and contain sufficient design storm containment capacity. The process ponds are operated with a freeboard sufficient capacity to provide for the flows from a 100 year storm and a total power outage. This results in an operational freeboard of 6 to 8 feet in the ponds.

Barrick Cortez

Name of Facility

Signature Lead Auditor

June 9, 2107

Date

Page 12 of 28

Standard of Practice 4.4:		Implement measures to protect birds, other wildlife and livestock from adverse effects of cyanide process solutions.			
	$\boxtimes$	in full compliance with			
The operation is		in substantial compliance with	Standard of Practice 4.4		
		not in compliance with			
<b>Basis for Audit Finding:</b>					
solutions containing cyani Netting on heap leach solu Eight foot high chain link	de. The ation co	different measures to restrict access bese measures consist of: (1) Perimeter onveyance ditches; (3) Bird ball floating around the process areas; and (5) Cyanide concentrations below 50 mg/L	r fencing around operation areas; (2) ing covers on all process ponds; (4) yanide destruction of the tailing		
supernatant ponds are to n	naintair	Area 28 tailings impoundment. Corton WAD cyanide levels below 50 mg/le and supernatant reclaim solution ar	L. Review of the 2014 - 2016 data		
•	nd supe	practices are effective in preventing vernatant pond and there were no mo	*		
runoff. Cortez has chang addition, Cortez has deve drainage The SOP "Pon operational requirements hour), and inspection req Additionally, this SOP in leach solution run off) con	ed its seloped ding of to mai quiremently actual to the contraction of	spray system to a drip system to re SOPs to address potential ponding in Leach Pad" provides a definition tain dripping within the lined area into of ramp for drainage inside and corrective measures if ponding is ed on haul roads to the heap leach page 2016 Re-certification Audit.	duce ponding in the leach cells. In on the heap leach pads and ramp on of significant ponding, outlines a (permitted up to 0.05 gallons per d outside the ditched lined facility. discovered. Water bars (to prevent		
Standard of Practice 4.5:		Implement measures to protect fish of indirect discharges of cyanide pro	0 0		
		in full compliance with			
The operation is		in substantial compliance with	Standard of Practice 4.5		
		not in compliance with			
Basis for Audit Finding:					
		Whitelb Giller			
Barrick Cortez Name of Facility		Signature Lead Auditor	June 9, 2107 Date		

Page 13 of 28

Cortez does not have any indirect discharge of cyanide solutions to surface waters. Cortez operates with zero discharge of process solutions. Cortez conducts monitoring of the seepage collection systems and leak detection systems to evaluate the integrity of these systems.

Standard of Practice 4.6:		Implement measures designed to manage seepage from cyanide facilities to protect the beneficial uses of groundwater.			
	$\boxtimes$	in full compliance with			
The operation is		in substantial compliance with	Standard of Practice 4.6		
		not in compliance with			

### **Basis for Audit Finding:**

Cortez has implemented solution management and seepage control systems to protect groundwater below and down gradient of the operation. There are also groundwater monitoring wells surrounding the ponds which are reviewed on a quarterly basis and reports sent to the regulatory Agency. The review of monitoring data for 2014-2016 indicates Cortez has not caused cyanide concentrations in groundwater to rise above levels protective of beneficial use.

The cyanide facilities are designed for zero discharge to both surface water and groundwater in accordance with NDEP regulations and Department of Interior Bureau of Land Management (BLM) Cyanide Management Policy and have all been constructed with impermeable containment systems or liners to prevent seepage.

All pipes, tanks, and other facilities at the Mill which convey process fluids containing cyanide are located within containment areas. Sumps within containment areas collect any spilled solution for return to the process.

The tailings impoundment is a fully lined facility with a liner system comprising of smooth, 60-mil HDPE synthetic primary liner placed over a minimum of 24 inches of clayey, second liner material.

Area 28 heap leach facility has a liner system consisting of a 60-mil HDPE synthetic primary liner placed over a 12-inch thick low hydraulic conductivity soil layer secondary liner. This Area has not been used as a Heap Leach facility during the recertification period and is considered inactive.

The Area 30 heap leach facility is constructed of either 60-mil or 80-mil HDPE liner placed over 12-inch thick low hydraulic conductivity soil layer (the 60-mil HDPE liner is used where the heap leach stacking height will not exceed 150 feet; and the 80-mil liner is used where the heap leach stacking height is approved for 300 feet.)

Area 34 Heap leach pads are constructed with a composite liner system comprised of a single layer of 80-mil double-textured HDPE geomembrane placed on a 12-inch thick Low Hydraulic Conductivity Soil Layer (LHCSL).

Barrick Cortez

Name of Facility

Signature Lead Auditor

June 9, 2107

Date

Page 14 of 28

Process components are equipped with leak detection systems. Leak detection systems are monitored on a regular basis.

Review of the Cortez environmental monitoring data (2014-2016 Quarterly Reports for WPCP NEV93109) indicates that the operation had either no detectable WAD cyanide (i.e. <0.01 mg/L) or very low concentrations (i.e. less than 0.05 mg/L).

Standard of Practice 4.7:		Provide spill prevention or containment measures for process tanks and pipelines.			
		in full compliance with			
The operation is		in substantial compliance with	Standard of Practice 4.7		
		not in compliance with			

### **Basis for Audit Finding**

Cortez has spill prevention and control systems for the cyanide offload areas, the associated storage tanks, and CIL and CIC tank process areas. Area 30, Area 28, Mill, and Area 34 offloading pads are constructed of cast-in-place reinforced concrete with curbed containments that report to sumps for return to the process. The Mill cyanide storage tank secondary containment system consists of concrete walls, approximately 7 feet high. The Area 28 cyanide tank is within a secondary curbed concrete containment with tertiary containment being the lined Reclaim Pond. Area 30 has two cyanide storage tanks that are located on a concrete curb and a drainage channel is provided to the barren pond for tertiary containment. The CIL/CIC/DETOX tank process areas have containment areas constructed of reinforced concrete. Area 34 has two cyanide storage tanks located in a reinforced concrete containment area with a drainage channel that allows for any excessive spillage (spillage exceeding the capacity of the sump pump) to flow through the process building to the barren pond. Cortez has automated pumps with level controls within the containments to pump collected solutions into the process circuits

Cortez has constructed all pipelines with spill prevention and containment measures to collect leaks and prevent releases. The pipelines are constructed either as pipe-in-pipe configuration and/or within lined ditches. The Mill uses a CIL circuit for primary gold extraction; and two CIC circuits are used for recovery of gold from clarified overflow solution and heap leach pregnant solution. All pipes, tanks, and other features in the Mill area which convey process fluids containing chemical reagents are located within containment areas. Sumps within containment areas collect any spilled solution for return to the circuit(s).

Tailings slurry is transported in a 14-inch diameter HDPE pipe. The pipe is placed between two earth berms, lined with HDPE, in a sloping roadway to the tailing impoundment. In the event of a tailings line failure, slurry is contained between the berms and flow is towards the tailing facility. The reclaim lines from the Area 28 Reclaim Pond to the Mill are also in doubled wall pipe or a containment system. Area 28 and Area 30 heap leach pad piping is either double walled HDPE pipe or is contained by lined system.

Barrick Cortez

Name of Facility

Signature Lead Auditor

June 9, 2107

Date

Page 15 of 28

Area 34 pregnant solutions (within the heap leach pad) are collected in a series of perforated and non-perforated pipes that discharge to a main collection header located in a lined pipeline channel at the down gradient edge of the pad. The main collection header collects pregnant solution and directs it to the process area.

Cortez uses steel and, HDPE pipelines, and HDPE lined steel which are compatible materials for the conveyance of high pH, cyanide solutions and slurries.

Standard of Practice 4.8:	Implement quality control/quality assurance procedures to confirm that cyanide facilities are constructed according to accepted engineering standards and specifications.		
	$\boxtimes$	in full compliance with	
The operation is		in substantial compliance with	Standard of Practice 4.8
		not in compliance with	

### **Basis for Audit Finding:**

Cortez has implemented and conducted QC/QA programs for construction of all cyanide facilities including the cyanide storage facilities, pipelines, conveyance ditches, process ponds, heap leach facilities and tailings impoundment facilities. QC/QA programs have been implemented for all new cyanide facilities and modifications made to existing facilities since the Initial Certification Audit and subsequent Re-certification Audits.

Cortez has implemented QC/QA programs for all earthworks projects related to tank foundations; compacted subgrades; clay liners; geomembrane liners; and ponds, tailings and heap leach facilities. These QC/QA reports include information on subgrade preparation, grading, soil liner material properties and compaction characteristics, soil liner hydraulic conductivity, leak detection construction, solution collection piping, geomembrane liner seams and testing. The construction documentation includes copies of the field inspection reports, laboratory and field data, construction observations, drawings, and photographs.

As with previous reviews of new construction documentation, review of the construction documentation during the 2016 Re-certification Audit showed that the new construction addresses the suitability of materials and adequacy of soil compaction for earthworks for tank foundations and earthen liners, the installation of synthetic membrane liners used in ponds and leach pads, and for construction of cyanide storage and process tanks.

Cortez has retained qualified engineering personnel to review and provide construction verification documentation. The QC/QA reports are stamped by Professional Engineers licensed in the State of Nevada. The QC/QA documents have also been reviewed and approved the NDEP.

Barrick Cortez /h/juhell Steller June 9, 2107
Name of Facility Signature Lead Auditor Date

Page 16 of 28

Standard of Practice 4.9:	Implement monitoring programs to evaluate the effects of cyanide use on wildlife surface and ground water quality.		
	$\boxtimes$	in full compliance with	
The operation is		in substantial compliance with	Standard of Practice 4.9
		not in compliance with	
Basis for Audit Finding			
Barrick Cortez Inc., Environ process solution and ground	nmen ndwa ter li	ntitled "Barrick Cortez Inc. Sampling at Department. This plan specifies the ter including sample preservation recests including cyanide species are a ions are included.	e standard operating procedures for quirements. Locations of sampling
annual refresher. Each er	nploy	ect for, watch for, and prevent wildlife ree is responsible for filing a report e mortality inspections are conducte	rt should they encounter wildlife
systems, leak detection systems analyzed on a quarterly based detection systems are pump	stems, sis. The ped on yees a	requencies adequate to characterize the wildlife, and process solutions. Growthe seepage collection systems are same a weekly basis and reported as a daily are outside on the property. Process so per day	andwater samples are collected and apled on a quarterly basis. The lead by average. The wildlife monitoring
PRINCIPLE 5 – DECOM	MMI	SSIONING	
		he environment from cyanide throug nissioning plans for cyanide facilities	· -
Standard of Practice 5.1:		Plan and implement procedures for e cyanide facilities to protect huma	
	$\boxtimes$	in full compliance with	
The operation is		in substantial compliance with	Standard of Practice 5.1
		not in compliance with	
<b>Basis for Audit Finding:</b>			
D 110		Whitell Giller	
Barrick Cortez Name of Facility		Signature Lead Auditor	June 9, 2107 Date

Page 17 of 28

Cortez has prepared closure plans as part of their permitting programs for the operations that have been reviewed and approval by the US Department of Interior Bureau of Land Management (BLM) and NDEP (for permits NEV0093109 and NEV2007106). The closure plan includes "Cortez Gold Mines (NVN-067575) 2011 Amendment to Plan of Operations (APO) and Reclamation Permit Applications", prepared August 2015. (This plan has been prepared for the Cortez Hills Complex and includes the area identified by the Cortez Operations as Area 34). The current approved APO is version #3.approved September 11 2015. The new version included extension of heap leach #30 and other non-cyanide related activities. (The expansion to Area #30 had not been constructed at the time of recertification.) Preparation of APO #4 was in progress for underground expansion and reportedly will not affect cyanide related facilities. Relevant sections of APO#3 were reviewed during the 2016 recertification.

The plans provide seasonal, temporary, and tentative final closure plans. The tentative final closure plans presents preliminary details for final closure of all project facilities following cessation of mining, heap leaching operations, and solution processing operations.

related decommissioning activities.

Establish an assurance mechanism capable of fully funding cyanide

Standard of Practice 5.2:

		o de la companya de	
	$\boxtimes$	in full compliance with	
The operation is		in substantial compliance with	Standard of Practice 5.2
		not in compliance with	
Basis for Audit Finding			
decommissioning activities "Cortez Gold Mines (NV Applications", prepared F (SRCE) to estimate the rethe entire Cortez Gold of Bureau of Mining Regular	s defind N-067: Sebruary clamation and in an incommunity of the second s	estimate for the funding of thined in the reclamation and closure periods 2015 Amendment to Plan of Cry 2015 and utilized the Nevada Station and closure costs. The estimated ins. The cost estimate has been revied & Reclamation and the BLM and Crapproving the updated surety amount	plans. The cost estimate is part of operations and Reclamation Permit ndard Reclamation Cost Estimator reclamation and closure cost is for ewed and approved by the Nevada Cortez has correspondence from the
PRINCIPLE 6 - WORK	ER S	AFETY	
Protect workers' health	and s	afety from exposure to cyanide.	
Standard of Practice 6.1:		Identify potential cyanide expo measures as necessary to eliminate, r	
		in full compliance with	
Barrick Cortez		Whihelb Gillen	June 9, 2107
Name of Facility		Signature Lead Auditor	Date

Page 18 of 28

The operation is		in substantial compliance with	Standard of Practice 6.1
		not in compliance with	
Basis for Audit Finding	g:		
the management and operation of the entire cowork. These procedures	eration of yanide ma are detail PPE) requi	Operating Procedures (SOPs) and crit the cyanide facilities. These plans an anagement facilities and cover decon- ed in the evidence observed section. irements, operator responsibilities, ar apdated regularly.	d procedures cover the safe camination prior to maintenance The documents describe Personal
the exposure to potential potentially involve cyan include maintenance act	lly toxic c ide expos ivities suc	by a flow chart decision making procedure would have a safety critical task per by the pump replacements, repairing per f cyanide containment areas.	his process all tasks that would procedure developed. Examples
impact on work health a	nd safety	ocess and operational changes and m are controlled under Barrick's Corpo procedure was adopted at Cortez in 2	orate online Management of Change
Worker input is actively	consider	ed during the development and roll or	ut of new procedures.
Standard of Practice 6.2	S	Operate and monitor cyanide facilition afety and periodically evaluate the enteressures.	<del>-</del>
	$\boxtimes$	in full compliance with	
The operation is		in substantial compliance with	Standard of Practice 6.2
_		not in compliance with	
Basis for Audit Finding	g:		
cyanide and that 'We ne maintained by adding lin	ed to mai ne predor	nd pH in Solution' procedure states that a pH over 10 and under 11.5'. The minantly at belt 3, although it can also thickener and detox reactor tank.	The SOP details that pH can be
column (CIC) area and t each of the Area 30 and	he grind o Area 34 I	in critical locations: the detox buildicircuit. Fixed monitors have also bee Heap Leach buildings on the ground to the Electrical and Instrumentation	n installed in identical locations in floor and then on floors 2 through
Barrick Cortez Name of Facility		Mihelb Lilke Signature Lead Auditor	June 9, 2107 Date

Page 19 of 28

calibration of the fixed monitors.

Warning signs have been placed in all areas where cyanide may be encountered, including offloading areas, and process tanks, and on all cyanide facilities warning that the tanks and pipes may contain cyanide solutions.

Showers and eyewash stations are located at the cyanide off- loading areas and throughout the process areas (in Area 30, 34 and the Mill). The showers and eye wash stations are inspected before every shift and before every off load. They are also inspected monthly as part of the preventative maintenance program and a record of the inspections are maintained.

Material Safety Data Sheets are available throughout the plant at any computer terminal via the site-wide. Poster boards are also posted around the workplace where cyanide is used including alarm levels, first aid, symptoms, locations of kits, cyanide storage facility locations. pH requirements in place to prevent off gassing.

The fixed monitors have warning lights at 4.7 ppm and a visible light and evacuation horn. These are alarmed in the central control room in the Mill, and at the controls rooms in Areas 30 and 34. The Area 30 and 34 alarms are also connected to the CCR as these areas may not consistently have an operator on duty. At a 4.7 ppm alarm the area is evacuated except for the Operator on duty that will investigate the alarm; at 10 ppm a full evacuation is initiated. Based on interviews with the Operators in the mill and Areas 30 and 34 there have been no alarms over 4.7 ppm in the last three years.

Bi-annual surveys were completed between 2014-2016. These included operators wearing badges for a 12 hour shift and recording any alarms above 4.7 ppm that occur. Both day and night shifts participate in the survey. No alarms above 4.7 were detected during the bi-annual surveys conducted in in 2014, 2015, and 2016.

Cortez also maintains handheld (MX-6 Multi-Gas monitors and Industrial Scientific GasBadge Promonitors). These HCN monitors are used when conducting specific activities where the risk of exposure may be higher, such as during a confined space entry procedure. Employees are able to sign out the gas badges as needed.

Cortez has procedures for accident and incident investigations associated with cyanide. These procedures include actions to determine the reason why the accident/incident occurred, and identify the corrective actions and/or controls to take to prevent similar occurrences in the future. There were no cyanide related incidents that required investigation in the previous three years.

Barrick Cortez /h/hhelb Lille June 9, 2107
Name of Facility Signature Lead Auditor Date

Page 20 of 28

Standard of Practice 6.3:	Develop and implement emergency response plans and procedures to respond to worker exposure to cyanide.		
	$\boxtimes$	in full compliance with	
The operation is		in substantial compliance with	Standard of Practice 6.3
		not in compliance with	

#### **Basis for Audit Finding:**

First aid procedures for cyanide poisoning along with general health and safety information on cyanide are presented on posters located in areas where cyanide is present. Additionally sSelf-contained breathing apparatus are held by the Emergency Response team in the event of alarms above 10.0 ppm. Cyanokits are stored in at locations around site where cyanide is present (Control #2 ambulance, Control #3 ambulance, laboratory complex, process mill control room, and Area 34 process and Area 30 Lunch room). Oxygen is also stored with kits.

First Responders are trained to use and know the location of the equipment and Cyanokits. The 'Off-loading Cyanide' procedure requires the driver of the cyanide transportation truck to report to the gate (Control #2) and pick-up a radio before proceeding to the off-load site. Additionally, video cameras are placed at each of the off-load sites allowing the Mill 2 Control Room to monitor off-load operations. When the cameras are not working a Mill 2 representative is required to be physically present during the entire off-load.

The Cyanokits, oxygen and emergency response vehicles are currently checked on a monthly basis by the Emergency Response team. The Cyanokits have a breakaway tag on them, as well as monthly inspection cards. Tags are punched during monthly inspections.

Other relevant monthly inspections conducted by Cortez include the AED, first aid rooms and emergency response vehicle which are inspected monthly by the emergency response team. Records of these inspections between 2014 and 2016 were randomly selected for review and appeared complete.

The Emergency Response Plan and relevant pre-plans detail specific written emergency response plans to respond to cyanide exposures.

Cortez has formal arrangements with Northeastern Nevada Regional Hospital through a commitment letter. The letter states that the hospital emergency department will readily receive and treat cyanide exposed patients. It also acknowledges that they keep in stock two cyanide poisoning kit with information and instruction material. The letter has been re-authorized in 2014, 2015 and 2016 to ensure currency of this acknowledgement.

Mock emergency drills are conducted annual to test response procedures for various cyanide exposure scenarios and debriefs are conducted following the drills to review the adequacy of these plans.

#### PRINCIPLE 7 - EMERGENCY RESPONSE

Barrick Cortez

Name of Facility

Signature Lead Auditor

June 9, 2107

Date

Page 21 of 28

Protect communities and the environment through the development of emergency response strategies and capabilities.

Standard of Practice 7.1:		Prepare detailed emergency response releases.	e plans for potential cyanide
	$\boxtimes$	in full compliance with	
The operation is		in substantial compliance with	Standard of Practice 7.1
		not in compliance with	

#### **Basis for Audit Finding:**

The emergency response plan details immediate actions to be taken in the event of an emergency spill which details cyanide separately. The emergency response plans include the anticipated roles and responsibilities of the Human Resources, Safety and Health, Environment, Security and other emergency response team (ERT) members as well as an updated list of the members of the ERT,

Additionally, the site has developed a cyanide release response pre-plan which is a comprehensive listing of all the potential types of emergencies related to cyanide, different levels of cyanide exposure and response requirements. The pre-plans are considered a supplement to the overall emergency response plan that is applicable for all emergencies across the site.

The Solid and Hazardous Waste Management Plan outlines the emergency procedures required for any situation involved hazardous waste, or the generation of hazardous waste such as the release of cyanide. It outlines emergency procedures as well as managing cyanide waste according to MSDS instructions, ensuring separation from acidic wastes and water. Preferred disposal of cyanide wastes is through the heap leach facilities to recycle the cyanide.

Plans contain procedures for potential scenarios such as: 1) catastrophic releases of cyanide; 2) accidents during cyanide transportation; 3) releases during offloading; 4) release of cyanide during fires and explosions; 5) pipe, valve or tank ruptures; 6) overtopping of ponds and impoundments; 7) power failure; 8) uncontrolled seepage; 9) tailings impoundment failure; 10) cyanide spill control and cleanup; and 11) decontamination and emergency evacuation.

Barrick Cortez

Name of Facility

Signature Lead Auditor

Date

Page 22 of 28

Standard of Practice 7.2:	Involve site personnel and stakeholders in the planning process.			
	$\boxtimes$	in full compliance with		
The operation is		in substantial compliance with	Standard of Practice 7.2	
		not in compliance with		
Basis for Audit Finding	g:			
Through participation on the uses cyanide at the operation	ne LEPo on and t	f the Lander County Local Emergency C these workers have been able to infect that it has prepared an ERP to address C for their use and reference.	form the community that Cortez	
procedures developed in th	e ERP.	rgency mock drills that allow them to Where possible Cortez has attempted duling issues have prevented this).		
uses cyanide and there is the	ne poter	Nevada Regional Hospital, in Elko in tial for cyanide exposed victims. The ow the proper procedure for treating of	e hospital has acknowledged that	
Standard of Practice 7.3:		Designate appropriate personnel and esources for emergency response.	commit necessary equipment and	
	$\boxtimes$	in full compliance with		
The operation is		in substantial compliance with	Standard of Practice 7.3	
		not in compliance with		
Basis for Audit Finding:				
departments: Human Reso well as representatives from	urces, S n proce lers are	rly laid out in the ERP including responder and Health, Environment, and sessing are part of the review team for trained in Advanced Medical First A	Security. These stakeholders, as the ERP when revisions are	
The ERP details call out pr	rocedure	es and 24 hour contact information for	or coordinators and team	
		n A I M NAM		
Barrick Cortez Name of Facility		Mihelb Liller Signature Lead Auditor	June 9, 2107 Date	

Page 23 of 28

#### members

Emergency response equipment, including Personal Protection Equipment, available on-site is detailed in the Emergency Response Equipment Needs section, this is sub divided into medical response, fire response, surface operations, fire equipment, high angle response, hazardous materials response equipment and underground operations.

The HAZMAT trailer, emergency response vehicle and the five Cyanokits are inspected monthly or quarterly to check all materials are available. This process is done by the emergency response team.

The ERP Assisting Agency Phone List includes contact numbers for Ambulance service, Clinic, Hospitals, Government agencies, MSHA, Nevada Division of Safety, Health and Training, Fire services, and Law enforcement

and Law enforcement.	encies,	MSHA, Nevada Division of Safety, I	Health and Training, Fire services,
Standard of Practice 7.4:		Develop procedures for internal and and and and and	external emergency notification
	$\boxtimes$	in full compliance with	
The operation is		in substantial compliance with	Standard of Practice 7.4
		not in compliance with	
Basis for Audit Finding:			
		ne List includes contact numbers for A MSHA, Nevada Division of Safety, I	
	kespers	tlined in the ERP includes identifications on. It is the Incident Commander's remedia.	•
Standard of Practice 7.5:	(	Incorporate into response plans and elements that account for the addition treatment chemicals.	9
	$\boxtimes$	in full compliance with	
The operation is		in substantial compliance with	Standard of Practice 7.5
		not in compliance with	
Basis for Audit Finding:			
The ERP Immediate Action	ons sect	tion titled 'In the event of a Chemical	Spill" and the "Sodium Cyanide
Barrick Cortez		While Giller	June 9, 2107
Name of Facility		Signature Lead Auditor	Date
			D 24 520

Page 24 of 28

Release or Exposure" sections of the ERP details that a solution of sodium hypochlorite (which should have a pH value of at least 8 but should not exceed a pH value of 10.5) should be available for use in decontamination procedures. Soft brushes should be available to remove contamination from PPE. Labelled, durable polyethylene bags should be available for disposal of contaminated PPE. The plan details in each Immediate Action scenario that the person in charge of the incident should coordinate reporting and clean-up activity with the Environmental Department.

The Solid and Hazardous Waste Management Plan details procedures for any accidents involving hazardous waste spills. The plan is designed to minimize hazards to human health or the environment from fires, explosions or any unplanned sudden or non-sudden release of hazardous waste or hazardous waste constituents to air, soil or surface water.

There are no natural surface water bodies on the property or adjacent to the property and treatment of a cyanide release to surface waters is not applicable

If evanide or process solution is spilled Cortez would follow their Incident Reporting and Investigation

processes; including 'conf	irmato	ry' sampling when required.	uoni rioporung unu mi osingunon	
Standard of Practice 7.6:		Periodically evaluate response procedures and capabilities and revise them as needed.		
	$\boxtimes$	in full compliance with		
The operation is		in substantial compliance with	Standard of Practice 7.6	
		not in compliance with		
Basis for Audit Finding:				
ERP on a regular basis and	d it has August	the the thick that the transfer of the transfe	ee 2011. The most recent full review	
person was medically affe	cted. Ir Hazma	rills occurred in 2016 involved an inc a 2015 the mock drill was related to a at drill included training on the Cyan	cyanide exposure due to a terrorist	
PRINCIPLE 8 – TRAIN	NING			
Train workers and environmentally pro-	_	ncy response personnel to manage of manner.	cyanide in a safe and	
Standard of Practice 8.1:	į	Train workers to understand the haz	ards associated with cyanide use.	
Barrick Cortez		Whitelb Giller	June 9, 2107	
Name of Facility		Signature Lead Auditor	Date	

**ERM** Page 25 of 28

	$\boxtimes$	in full compliance with	
The operation is		in substantial compliance with	Standard of Practice 8.1
		not in compliance with	
Basis for Audit Finding	g:		
includes a PowerPoint p	resentatio	yanide safety as part of Cortez's fou on called Cyanide Training. Cortez re hat includes cyanide training	
process (i.e. all mill emy which includes the safe mill workers are trained beginning work in the d and elutions. The manual	ployees, luse and he for a job esignated als are detailed.	cific areas of operations where cyanic each pad operators etc.) are given 20 andling of cyanide with on the job do including instruction related to cyanic area. Detailed training manuals exist tailed and have clear instructions with actor inductions required before any page 20.	hours 'onboarding' training lepartmental training. For example, nide use and handling, before at for operation in detox, grind CIL th pictures and annotations.
a component on cyanide			person can access the site, includes
record and track training print out from the LMS audit by requesting certa	and has a outlining ain employ	nline Learning Management System a searchable functionality. The LMS completed training, a review of the I yees training records and then backtovere met. The LMS proved effective	continues to be used. In addition to LMS was conducted during the cacking through the system to
Standard of Practice 8.2		Train appropriate personnel to operoystems and procedures that prommunity and the environment.	
	$\boxtimes$	in full compliance with	
The operation is		in substantial compliance with	Standard of Practice 8.2
		not in compliance with	
Basis for Audit Finding	g:		
		as where cyanide is an integral part o vities, are trained on the safe use and	-
job training and is provi	ded by a	and job departmental training, the pri competent person. The employee is it es. The level of competency is track	instructed on the proper use of the
Barrick Cortez Name of Facility		Mihelb Liber Signature Lead Auditor	June 9, 2107 Date

Page 26 of 28

which requires certain competencies to advance to the next level. There are progression booklets that are required to be completed by the Supervisor and then uploaded into the LMS.

Cortez requires all workers to have an annual refresher training (ART) that includes cyanide training. All training record sheets have been maintained with the applicable information and maintained in hard copy since at least 2010 and in soft copy within the LMS.

Stanaara of Practice 8.3:	exposures and environmental releases of cyanide.		
	$\boxtimes$	in full compliance with	
The operation is		in substantial compliance with	Standard of Practice 8.3
		not in compliance with	

#### **Basis for Audit Finding**

Workers involved in the use and handling of cyanide, such as unloading, mill operations, and maintenance, are trained on the risks and proper handling techniques including decontamination and first aid procedures. The training uses process training manuals and SOPs and includes instruction on decontamination and first aid procedures for cyanide release incidents. Mill workers receive annual cyanide refresher training that demonstrates procedures to follow in the event of cyanide release. First aid and CPR and oxygen training is provided to any Cortez employee that requests it and on a voluntary basis. This is a continuous process and includes Mill employees.

Cortez has provided a copy of the Emergency Response Plan to the Lander County LEPC. Additionally, Cortez has formal arrangements with the Northeast Nevada Regional Hospital to provide assistance in the event of a cyanide related incident.

Since 2010 Cortez Process department has a monthly work order to conduct mock drills. The form 'Cyanide Emergency Mock Drill' details the drill date, location, overview, participants, and objectives, it has a check list of all items covered in the drill, such as emergency call, checking wind direction, first aid details, the form requires a list of corrective actions needed to improve awareness and emergency readiness. In addition periodic (annual) mock drills on a larger scale are undertaken which include cyanide related incident.

Emergency Response Coordinators and members of the ERT (First Responders) are trained on the procedures and guidelines outlined in the ERP such as the response to a cyanide spill, release, or emergency. Training also includes the use of the, SCBA, and other PPE necessary to respond to a cyanide emergency. In addition there are Advanced EMTs on each shift that are able to administer the Cyanokit.

The site also holds annual mock emergency which cover both worker exposure and environmental releases. The drills are evaluated to review the adequacy of these plans and a training perspective to determine if personnel have the knowledge and skills required for effective response and training procedures are updated where needed. Documentation of the debriefs are retained on site. The records of completed training are maintained in the LMS database.

Barrick Cortez

Name of Facility

Signature Lead Auditor

June 9, 2107

Date

Page 27 of 28

### PRINCIPLE 9 – DIALOGUE

TRICON EL 9 DE LE	JGCL		
Engage in public consult	ation a	and disclosure.	
Standard of Practice 9.1:	ì	Provide stakeholders the opportunity	to communicate issues of concern.
	$\boxtimes$	in full compliance with	
The operation is		in substantial compliance with	Standard of Practice 9.1
		not in compliance with	
<b>Basis for Audit Finding:</b>			
community meetings and a workers attend civic activi- the minutes of the meeting were no members that hav Landowners and local trib	also attaties what we brought the brought	nt participate in periodic Town of Cre end Local Emergency Planning Commerce they interact with the general pub- were reviewed cyanide was not a spec- ght this issue up as a concern.  The ability to participate in any of f groups had received tours, including ment bodies	mittee (LEPC) meetings. They and lic and public officials. Based on ific topic of discussion, as there the public tours that are offered.
Standard of Practice 9.2:	1	Initiate dialogue describing cyanide i responsively address identified conce	
	$\boxtimes$	in full compliance with	
The operation is		in substantial compliance with	Standard of Practice 9.2
		not in compliance with	
Basis for Audit Finding:			
•		h scheduling site tours. Numerous visears including the Nevada Mining Ass	•
induction prior to participa	ating in	xplanation about the Cyanide Code and a tour. These visits present visitors we wide the company with the opportunit	ith the opportunity to ask questions
Information on use of cyar Report.	nide at	the Barrick sites is included in the An	nual Barrick Responsibility
Barrick Cortez		Whitell Gillen	Juna 0, 2107
Name of Facility		Signature Lead Auditor	June 9, 2107 Date

Page 28 of 28

Standard of Practice 9.3:		Make appropriate operational and environmental information regarding cyanide available to stakeholders.	
	$\boxtimes$	in full compliance with	
The operation is		in substantial compliance with	Standard of Practice 9.3
		not in compliance with	

### **Basis for Audit Finding:**

Any incident requiring regulatory reporting as per the Solid and Hazardous Waste Management Plan or the ERP would become publicly available through freedom of information processes. In addition, any such incidents would be discussed during the quarterly meetings with the local landowners and tribes. The Cortez Water Pollution Control Permit (WPCP) and accompanying Fact Sheet that describes the use and management of cyanide at the site are public documents that are available from Cortez or from the Nevada Department of Environmental protection (NDEP). Also, WPCP Quarterly Monitoring Reports are available to the public. These documents outline Cortez's use of cyanide.

Barrick Cortez

Name of Facility

Signature Lead Auditor

Date

Page 29 of 28