



May 18th, 2026

Agnico Eagle Mine – Meadowbank Complex- 2025 ICMC Audit – Corrective Action Plan

To whom it may concern,

This corrective action plan has been created to address the comments raised by the ICMI regarding the **Standard of Practice 6.2.5** “Have warning signs been placed where cyanide is used advising workers that cyanide is present, of any necessary personal protective equipment that must be worn and that smoking, open flames and eating are not allowed” & **Standard of Practice 6.2.8** “Are unloading, storage, mixing and process tanks and piping containing cyanide solution identified to alert workers of their contents, and is the direction of cyanide flow in pipes designated”.

While all areas around the milling facility comply with these standards. Sections of the tailings facility, tailings piping and water reclaim line are missing the required signage. Agnico Eagle will proceed with the installation of additional tailings warning signs, identical to the photo below (see figure 1) along the sections of the active tailings line where warning signs are missing. In addition, installation of similar signs will occur along the water reclaim lines from the Tailings Storage Facility to the Milling Facility. The addition of arrows indicating the direction of flow within the piping. Signs and arrows will be placed every 50ft along the line.

The addition of warning signage at the entrances to the Tailings Storage Facility to meet the requirements of Standard of Practice 6.2.5 will also be completed.

Agnico Eagle is committed to correcting both deficiencies by **September 30th, 2026**.



Figure 1: Intended signage along the active tailing's lines