

INTERNATIONAL CYANIDE MANAGEMENT INSTITUTE

Auditor Credentials Form

For The
International Cyanide Management Code

www.cyanidecode.org

July 2005

The International Cyanide Management Code (hereinafter "the Code"), this document, and other documents or information sources referenced at www.cyanidecode.org are believed to be reliable and were prepared in good faith from information reasonably available to the drafters. However, no guarantee is made as to the accuracy or completeness of any of these other documents or information sources. No guarantee is made in connection with the application of the Code, the additional documents available or the referenced materials to prevent hazards, accidents, incidents, or injury to employees and/or members of the public at any specific site where gold is extracted from ore by the cyanidation process. Compliance with this Code is not intended to and does not replace, contravene or otherwise alter the requirements of any specific national, state or local governmental statutes, laws, regulations, ordinances, or other requirements regarding the matters included herein. Compliance with this Code is entirely voluntary and is neither intended nor does it create, establish, or recognize any legally enforceable obligations or rights on the part of its signatories, supporters or any other parties.

Auditor Credentials Form

Facility Audited: Pierina Gold Mine, Peru Date: 28-31 Oct 2013

Lead Auditor Credentials

Lead Auditor: Alistair Cadden Auditor Certification Number: 12619

Certifying Organization: Institute of Environmental Management and Assessment (IEMA)

Telephone Number .: +44 1522 54009

Address: St Nicholas House, 70 Newport, Lincoln, LN1 3DP, UK Web Site Address: www.iema.net

Minimum experience: 3 Audits in past 7 years as Lead Auditor

Year	Type of Facility, Type of Audit Led	Country & State/Province	
2007	Lichkvaz Tey Gold Mine health and safety audit	Meghri, Armenia	
2008	Lega Dembi Gold Mine, tailings dam safety and cyanide management	Shakisso Ethiopia	
2008	Tulawaka Gold Mine, ICMI Cyanide code compliance audit	Tulawaka, Tanzania	
2008	Bulyanhulu Gold Mine, ICMI Cyanide code compliance audit	Bulyanhulu, Tanzania	
2009	Pokrovskiy Gold Mine, ICMI Gap Analysis audit	Amur Oblast, Russian Federation	
2009	Pioneer Gold Mine, ICMI Gap Analysis audit	Amur Oblast, Russian Federation	
2009	Porcupine Gold Mines gap analysis audit	Timmins, Ontario, Canada	
2009	Red Lake Gold Mines gap analysis audit	Red Lake, Ontario, Canada	
2010	Cero Vanguardia Gap Analysis	Santa Cruz, Argentina	
2010	Bisha Gold Mine Tailings Audit	<u>Eritrea</u>	
<u>2010</u>	Porcupine Gold Mines ICMI compliance audit	Timmins, Ontario, Canada	
2010	Red Lake Gold Mines ICMI compliance audit	Red Lake, Ontario, Canada	
2010	Pierina Gold Mine Recertification Audit	Huaraz, Peru	
2010	Lagunas Norte Gold Mine Recertification Audit	Santiago de Chuco, Peru	
2011	Veladero Gold Mine Recertification Audit	San Juan, Argentina	
2011	El Sauzal Gold Mine Certification Audit	Hermosillo, Mexico	
2011	Cerro Vanguardia Gold Mine Certification Audit	Santa Cruz, Argentina	
2013	Porcupine Gold Mine recertification	Timmins, Ontario	
2013	Pierina Gold Mine Recertification Audit	Huaraz, Peru	
2013	Lagunas Norte Gold Mine Recertification Audit	Santiago de Chuco, Peru	

Cyanide-related Operations Experience

Each auditor must have at least 3 years; at least one auditor must have at least 7 years experience

Auditor	Yrs.	Relevant Position Titles	Types of Operations
Alistair Cadden	18	Principal, Geotechnical Engineer	CIL/CIP/RIP plants; Heap Leach Operations Base metals flotation plants
Adolfo Mesones	7	Senior Project Engineer	CIL/CIP/RIP plants; Heap Leach Operations; Base metals flotation plants

Statement of No Conflict

I certify that I have not audited any component of this facility for which I was responsible for design or development; nor have I within the past year been an employee of the facility, its parent company, or associated affiliates. Excluding audits, I have not derived more than 30% of my income within the past 5 years from the facility, its parent, or associated affiliates. I have not participated in more than two consecutive Cyanide Code audits of this facility. I have participated in at least 3 health, safety, and/or environmental audits in the past 7 years and am familiar with standard audit procedures as well as with the protocols developed by the International Cyanide Management Institute for implementation of the Code.

Signed,	Name Signature	Date
Lead Auditor*	Alistair Cadden MHAV Call	9 th June 2014
Auditor 1	Adolfo Mesones	9 th June 2014



Av. Aramburú 668 Surquillo, Lima, Perú Central Telefónica: 618.5151 alfredo@notariapaino.com.pe www.notariapaino.com



ALFREDO PAINO SCARPATI Notario de Lima

