

INTERNATIONAL CYANIDE MANAGEMENT INSTITUTE Auditor Credentials Form

Facility Audited:

Red Lake Gold Mines, Red Lake, Ontario

Date:

February 27 to March 2, 2017

Auditor and Technical Specialist Credentials:

Lead Auditor:

Evan Jones

Auditor Certification Number:

12169

Certifying Organization:

Canadian Environmental Certification Approvals Board

Telephone Number:

+1 (403) 233-7484

Address:

Suite 200, 308 – 11th Avenue SE, Calgary, Alberta, Canada, T2G 0Y2

Web Site Address:

www.cecab.org

Minimum Experience:

3 Audits in past 7 years as Lead Auditor

| Year | Type of Facility, Type of Audit Led | Country | | |
|------|---|------------------------------|--|--|
| 2011 | Marlin Safety MS Audit | San Miguel , Guatemala | | |
| 2011 | Eleonore Safety MS Audit | James Bay, Quebec, Canada | | |
| 2011 | Penasquito Safety MS Audit | Zacatecas, Mexico | | |
| 2012 | ATCO Battle River Generating Station EMS Audit | Forestburg, Alberta, Canada | | |
| 2012 | Canadian Pacific Rail Safety Audit | Lethbridge, Alberta, Canada | | |
| 2012 | Musselwhite Safety MS Audit | Thunder Bay, Ontario, Canada | | |
| 2012 | Porcupine Gold Mines Safety MS audit | Timmins, Ontario, Canada | | |
| 2013 | Talvivaara Safety MS Audit | Sotkamo, Finland | | |
| 2013 | El Sauzal Safety MS Audit | Chihuahua, Mexico | | |
| 2013 | Wharf Mine Safety MS Audit | Lead, South Dakota, USA | | |
| 2013 | Teck Fording Coal EHS Compliance Audit | Sparwood, BC, Canada | | |
| 2013 | Porcupine Gold Mines Recertification Audit | Timmins, Ontario, Canada | | |
| 2013 | Red Lake Gold Mine Recertification Audit | Red Lake, Ontario, Canada | | |
| 2013 | Rubicon Phoenix Gold Project Design Review | Red Lake, Ontario, Canada | | |
| 2014 | Penasquito Safety MS Audit | Zacatecas, Mexico | | |
| 2014 | Guyana Goldfields Aurora Project Safety / IFC Audit | Cuyuni-Mazaruni, Guyana | | |
| 2014 | Red Lake Safety MS Audit | Red Lake, Ontario, Canada | | |
| 2015 | Los Filos Safety MS Audit | Guerrero, Mexico | | |
| 2015 | Guyana Goldfields Aurora Project Safety / IFC Audit | Cuyuni-Mazaruni, Guyana | | |
| 2016 | Musselwhite Safety MS Audit | Thunder Bay, Ontario, Canada | | |





Red Lake Gold Mines, Red Lake, Ontario, Canada Recertification Audit

| Year | Type of Facility, Type of Audit Led | Country | | |
|------|---|------------------------------|--|--|
| 2016 | Musselwhite Recertification Audit | Thunder Bay, Ontario, Canada | | |
| 2016 | Los Filos Change Management Process Review | Guerrero, Mexico | | |
| 2016 | Guyana Goldfields Aurora Project Safety / IFC Audit | Cuyuni-Mazaruni, Guyana | | |
| 2016 | Areva McClean Lake EHS Compliance Audit | Saskatchewan, Canada | | |
| 2016 | Eleonore Safety MS Audit | James Bay, Quebec, Canada | | |
| 2016 | Porcupine Gold Mines Safety MS Audit | Timmins, Ontario, Canada | | |
| 2017 | Cripple Creek and Victor Mines Gap Assessment | Cripple Creek, Colorado, USA | | |
| 2017 | Red Lake Gold Mine Recertification Audit | Red Lake, Ontario, Canada | | |
| 2017 | Porcupine Gold Mines Recertification Audit | Timmins, Ontario, Canada | | |

Cyanide-related Operations Experience

Each auditor must have at least 3 years; at least one auditor must have at least 7 years' experience.

| Auditor | Yrs. | Relevant Position Titles | Types of Operations | | |
|---------------|------|--|---|--|--|
| Evan Jones | 10 | Registered Professional Engineer (Bio-Resource); Associate, Senior EHS Practitioner; Certified Environmental Auditor | Evan has worked as an EHS consultant with the mining industry since 2004, and on cyanide-related projects since 2007. He is involved with auditing of EHS programs, compliance audits, due diligence audits, and safety and environmental program development. His experience includes CIL/CIP/RIP plants, heap leach operations, and base metals flotation plants. | | |
| Ivon Aguinaga | 15+ | Senior Engineer | Since 2000, Ivon has worked in the mining industry as a consulting engineer with emphasis on environmental mine permitting, regulatory compliance auditing, surface water engineering, environmental impact assessments and baseline studies. | | |





Red Lake Gold Mines, Red Lake, Ontario, Canada Recertification Audit

Statement of No Conflict

I certify that I have not audited any component of this facility for which I was responsible for design or development; nor have I within the past year been an employee of the facility, its parent company, or associated affiliates. Excluding audits, I have not derived more than 30% of my income within the past 5 years from the facility, its parent, or associated affiliates. I have not participated in more than three consecutive Cyanide Code audits of this facility. I have participated in at least three health, safety, and/or environmental audits in the past 7 years and am familiar with standard audit procedures as well as with the protocols developed by the International Cyanide Management Institute for implementation of the Code.

| Signed | Name | Signature | Date | | |
|-----------------------------|---------------|---------------|---------------|--|--|
| Lead Auditor* | Evan Jones | 9//~ | July 10, 2017 | | |
| Mining Technical Specialist | Ivon Aguinaga | huin Apingac. | July 10, 2017 | | |

Use additional pages if necessary

| Subscribed and sworn (or affirmed) before me this | [Day] | _ day | July [Month] | _, 20 <u>7</u> |
|---|-------|--------------|--------------|----------------|
| by Scott Ferguson. [Name of Signer] | | 2 | 1 | |
| | | [Notary Sign | | |

^{*}The lead auditor's signature must be certified by notarization or equivalent.