INTERNATIONAL CYANIDE MANAGEMENT INSTITUTE

Auditor Credentials Form

Facility Audited: Marlin Mine, Guatemala

Date: June 22, 2009

Lead Auditor and Technical Expert Credentials

Lead Auditor: Pamela J. Stella, P.G., CEA

Auditor Certification Number: 9754

Golder Associates Inc.

Telephone Number: (303) 980-0540

44 Union Blvd Suite 300

44 Union Blvd., Suite 300 Lakewood, CO 80228

Certifying Organization: National Registry of Environmental Telephone Number.: (847) 724-6631

Professionals (NREP)

Address: PO Box 2099, Glenview, IL 60025 Web Site Address: www.nrep.org

Minimum experience: 3 audits in past 7 years as Lead Auditor

Year	Type of Facility, Type of Audit Led	Country & State/Province
2009	Confidential gold mine and milling facility. Lead Auditor for Gap analysis audit for compliance with the ICMC. Audit followed ICMI verification protocol and included development of detailed audit report and action plan.	Argentina
	Newmont Mining Corporation Carlin Mine. Lead Auditor for the verification audit for compliance with the ICMC. Audit followed the ICMI verification protocols for Gold Mining Operations.	Nevada, USA
	Confidential gold heap leach facility. Lead Auditor for Gap analysis audit for compliance with the ICMC. Audit followed ICMI verification protocol and included development of detailed audit report and action plan.	Mexico
2008	Newmont Mining Corporation Phoenix Mine. Lead Auditor for the verification audit for compliance with the ICMC. Audit followed the ICMI verification protocols for Gold Mining Operations.	Nevada, USA
	Goldcorp Inc. El Sauzal Mine. Lead Auditor for the verification audit for compliance with the ICMC. Audit followed the ICMI verification protocols for Gold Mining Operations.	Los Mochis, Mexico
	Newmont Mining Corporation Minera Yanacocha Mine. Technical Mining Expert Auditor for the verification audit for compliance with the ICMC. Audit followed the ICMI verification protocols for Gold Mining Operations.	Cajamarca, Peru
	Pogo Gold Mine. Lead auditor for third-party compliance audit of the gold mines and CIL beneficiation involving cyanidation and cyanide destruction process. Results of the audit were to assist in determining if the Environmental Management Systems of the company and the regulatory controls applicable to the mine provide reasonable assurance that environmental objectives are being met and that they systems and controls are functioning as intended. The audit was a 5-year environmental compliance audit required by the agencies.	Alaska
	Confidential gold mill tailings facility. Technical Mining Expert Auditor for Gap analysis and verification audit for compliance with the ICMC. Audit followed ICMI verification protocol and included development of detailed audit report and action plan.	Ontario, Canada

2008	Confidential gold mill tailings facility. Technical Mining Expert Auditor for Gap analysis and verification audit for compliance with the ICMC. Audit followed ICMI verification protocol and included development of detailed audit report and action plan.	Ontario, Canada
	Confidential gold mill tailings facility. Technical Mining Expert Auditor for Gap analysis and verification audit for compliance with the ICMC. Audit followed ICMI verification protocol and included development of detailed audit report and action plan.	Ontario, Canada
2007	Barrick Gold Corporation Ruby Hill Mine. Technical Mining Expert Auditor for the verification audit for compliance with the ICMC. Audit followed the ICMI verification protocols for Gold Mining Operations.	Nevada, USA
	Newmont Mining Corporation Lone Tree Mine. Technical Mining Expert Auditor for the verification audit for compliance with the ICMC. Audit followed the ICMI verification protocols for Gold Mining Operations.	Nevada, USA
	Barrick Gold Corporation Goldstrike Mine. Technical Mining Expert Auditor for the verification audit for compliance with the ICMC. Audit followed the ICMI verification protocols for Gold Mining Operations.	Nevada, USA
	Confidential gold mill tailings facility. Technical Mining Expert Auditor for Gap analysis and verification audit for compliance with the ICMC. Audit followed ICMI verification protocol and included development of detailed audit report and action plan.	Guatemala
	Technical Mining Expert Auditor for Gap analysis and verification audit for compliance with the ICMC. Audit followed ICMI verification protocol and included development of detailed audit report and action plan.	Chile
2006	Marigold Gold Mine. Technical Mining Expert Auditor for the verification audit for compliance with the ICMC. Audit followed the ICMI verification protocols for Gold Mining Operations.	Nevada, USA
2006	Confidential gold cyanide heap leach facility and two tailing storage facilities – Auditor for corporate environmental audits.	Mexico, Guatemala, Honduras
2006	Confidential gold cyanide heap leach facility – Technical Expert for gap analysis and verification audit for compliance with the ICMC. Audit followed ICMI verification protocol and included development of detailed audit report and action plan.	Nevada, USA
2005	Barrick Gold Corporation La Pierina Gold Mine. Lead Auditor for Cyanide Pre-verification compliance audit for the International Cyanide Management Code of a gold cyanide heap leach facility. The audit followed the Code's principles and practices. Daily meetings were held with the key mine management staff to discuss the audit findings and information requests. Technical Auditor for handling, storage, operations, safety, emergency response, training and public consultation.	Peru
2004	Barrick Gold Corporation Gold Strike Mine. Lead Auditor for Cyanide Pre-verification compliance audit for the International Cyanide Management Code of a gold cyanide heap leach facility. The audit followed the Code's principles and practices. Daily meetings were held with the key mine management staff to discuss the audit findings and information requests. Technical Auditor for handling, storage, operations, safety, emergency response, training and public consultation.	Nevada

Cyanide-related Operations Experience

Each auditor must have at least 3 years; at least one auditor must have at least 7 years experience

Auditor	Yrs.	Relevant Position Titles	Types of Operations
Pamela J. Stella, C.E.A.,	24	Senior Mining	Since 1989, Ms. Stella has provided
P.G.		Environmental Consultant	environmental services to gold mine
Masters of Science			operations worldwide. She is the
Geology			National Mining Environmental
			Coordinator for Golder Associates
			Inc. and spends approximately 90% of
			her time providing the following
			services to gold operations:
			compliance auditing, mine permitting,
			ground and surface water
			management, development of
			environmental management plans,
			contingency plans and health and
			safety plans, project manager for
			bankable environmental baseline
			studies and environmental impact
			assessments for gold mining
			operations (exploration through
			closure) to local regulations,
			international best practices and World
			Bank guidelines. Her former career
			as a registered nurse allows her to
			fully evaluate health and safety issues.
			Her technical background is in
			geology and water resources.
G. Ivón Aguinaga	8	Senior Project Engineer,	Ms. Aguinaga has over 8 years of
Civil Engineer,		Mining Group,	experience in mining environmental
M.Sc. in Environmental		Golder Associates Inc.	projects involving all phases of
Science and Management.			mining development and operation.
			Approximately 75% of her experience
			has been spent with gold operations.
			This experience includes: compliance
			auditing, mine permitting,
			development of mine water balances,
			environmental studies, review of
			budgets and schedules for mining
			environmental projects, and
			environmental management plans
			(e.g., environmental contingency
			plans and occupational health and
			safety plans). She has been involved
			in several multidisciplinary
			environmental impact assessment
			projects and environmental baseline
			studies for mining operations.

Statement of No Conflict

I certify that I have not audited any component of this facility for which I was responsible for design or development; nor have I within the past year been an employee of the facility, its parent company, or associated affiliates. Excluding audits, I have not derived more than 30% of my income within the past 5 years from the facility, its parent, or associated affiliates. I have not participated in more than two consecutive Cyanide Code audits of this facility. I have participated in at least 3 health, safety, and/or environmental audits in the past 7 years and am familiar with standard audit procedures as well as with the protocols developed by the International Cyanide Management Institute for implementation of the Code.

Signed	Name	Signature	Date
Lead Auditor*	Pamela J. Stella, CEA	amel Della	08/07/09
Auditor	G. Ivón Aguinaga	Ivon Aguinaga C	08/07/09

Use additional pages if necessary

State of Colorado

My commission expires:

^{*}The lead auditor's signature must be certified by notarization or equivalent.