

INTERNATIONAL CYANIDE MANAGEMENT INSTITUTE Auditor Credentials Form

Facility Audited: Phoenix Mine, Nevada, United States of America

Date: February 9 to 12, 2015

Auditor and Technical Specialist Credentials:

Lead Auditor: Kent R. Johnejack

Auditor Certification Number: Certified Environmental Auditor No. 35173

Certifying Organization: National Registry of Environmental Professionals (NREP)

Telephone Number: (847) 724-4223

Address: P.O. Box 2099, Glenview, IL, United States of America

Web Site Address: www.nrep.org

Minimum Experience: 3 Audits in past 7 years as Lead Auditor

Year	Type of Facility, Type of Audit Led	Country		
Mining – International Cyanide Management Code Pre-Signatory Services (Design Reviews)				
2013	Mining Technical Specialist for Rubicon Phoenix Mine	Ontario, Canada		
2015	Mining Technical Specialist for Newmont Long Canyon Mine	Nevada, USA		
Mining – International Cyanide Management Code Pre-Certification Audits (Gap Analyses)				
2009	Mining Technical Specialist for Peńoles La Herradura Mine	Sonora, Mexico		
2011	Mining Technical Specialist for GoldCorp Wharf Mine South Dakota, US			
2011	Lead Auditor and Mining Technical Specialist for GoldCorp Peñasquito Mine	Zacatecas, Mexico		
2013	Lead Auditor and Mining Technical Specialist for GoldCorp Los Filos Mine	Guerrero, Mexico		
2013	Lead Auditor and Mining Technical Specialist for Newmont Yanacocha Mine	Cajamarca, Peru		
2014	Lead Auditor and Mining Technical Specialist for Newmont Emigrant Mine	Nevada, USA		
Mining – International Cyanide Management Code Certification Audits (Initial or Recertification)				
2010	Mining Technical Specialist for Newmont Twin Creeks Mine	Nevada, USA		
2010	Mining Technical Specialist for Barrick Lagunas Norte Mine	Santiago de Chuco, Pe		
2011	Mining Technical Specialist for Peñoles La Herradura Mine	Sonora, Mexico		
2011	Mining Technical Specialist for Newmont Yanacocha Mine	Cajamarca, Peru		
2011	Lead Auditor and Mining Technical Specialist for Newmont Phoenix Mine	Nevada, USA		
2012	Lead Auditor and Mining Technical Specialist for Newmont Carlin Mine	Nevada, USA		
2012	Lead Auditor and Mining Technical Specialist for Goldcorp Peñasquito Mine	Zacatecas, Mexico		
2012	Lead Auditor and Mining Technical Specialist for Goldcorp Wharf Mine	South Dakota, USA		
2012	Lead Auditor and Mining Technical Specialist for Minas de Oro Mulatos Mine	Sonora, Mexico		
2013	Lead Auditor and Mining Technical Specialist for Goldcorp Los Filos Mine	Guerrero, Mexico		
2013	Lead Auditor and Mining Technical Specialist for Goldcorp Red Lake Gold Mines	Ontario, Canada		
2014	Lead Auditor and Mining Technical Specialist for New Gold Cerro de San Pedro Mine	San Luis Potosi, Mexico		
2014	Lead Auditor and Mining Technical Specialist for Peñoles La Herradura Mine	Sonora, Mexico		





Phoenix Mine, Nevada, USA Recertification Audit

Year	Type of Facility, Type of Audit Led	Country			
2014	Lead Auditor and Mining Technical Specialist for Newmont Yanacocha Mine	Cajamarca, Peru			
2014	Lead Auditor and Mining Technical Specialist for Goldcorp El Sauzal Mine	Chihuahua, Mexico			
2014	Lead Auditor and Mining Technical Specialist for Barrick Pueblo Viejo Mine	Cotui, Dominican Repul			
	Mining – Regulatory Compliance Audits				
2012	Lead Auditor for Regulatory Compliance Audit at Thompson Creek Mine	Idaho, USA			
Due Diligence and Regulatory Assessments					
2005	Project Manager for Due Diligence Assessment of the ASARCO Ray Mine against Arizona Groundwater Regulations, Surface Water Regulations, and Best Available Demonstrated Control Technology (BADCT) Requirements	Arizona, USA			
2008- 2010	Lead Inspector for Monthly Stormwater Inspections for Compliance with Aquifer Protection Permit No. P-101703 at the West Plant Site of the Superior Mine	Arizona, USA			
2011	Lead Inspector for Non-Stormwater Discharge Inspection of the Copper Basin Mine with respect to Arizona Multi-Sector General Permit requirements.	Arizona, USA			
2012	Lead Assessor for Five-Year Inspection of Best Available Demonstrated Technology (BADCT) Requirements at Closed Facilities for Compliance with Aquifer Protection Permit No. P-101703 at the West Plant Site of the Superior Mine	Arizona, USA			
2012	Inspector for petroleum facilities and oil-filled equipment at the Copper Queen Branch as part of updating the Spill Prevention, Control, and Countermeasure Plan	Arizona, USA			

Cyanide-related Operations Experience

Each auditor must have at least 3 years; at least one auditor must have at least 7 years' experience.

Auditor	Yrs.	Relevant Position Titles	Types of Operations
Kent R. Johnejack	20+	Registered Professional Engineer (Civil); Senior Engineer/Principal; and Certified Environmental Auditor	Since 1995, Kent has worked in the mining industry as a consulting engineer and hydrologist. He has been involved with groundwater and surface water permitting, closure, remediation, spill cleanup, due diligence, waste characterization, sampling and analysis, civil design, construction oversight, regulatory compliance inspections, and auditing. Prior to 1995, Kent worked in land development, infrastructure, and low-level radioactive waste projects.
Ivon Aguinaga	13+	Senior Engineer	Since 2000, Ivon has worked in the mining industry as a consulting engineer with emphasis on environmental mine permitting, regulatory compliance auditing, surface water engineering, environmental impact assessments and baseline studies.
Rick Frechette	20+	Registered Professional Engineer (Geotechnical) and Senior Vice President of Environmental Services (Knight Piesold Inc.)	Rick Frechette participated as an independent auditor on selected aspects of Standards of Practice 4.3 and portions of 4.8 to avoid a Golder conflict of interest.



Phoenix Mine, Nevada, USA Recertification Audit

Statement of No Conflict

I certify that I have not audited any component of this facility for which I was responsible for design or development; nor have I within the past year been an employee of the facility, its parent company, or associated affiliates. Excluding audits, I have not derived more than 30% of my income within the past 5 years from the facility, its parent, or associated affiliates. I have not participated in more than three consecutive Cyanide Code audits of this facility. I have participated in at least three health, safety, and/or environmental audits in the past 7 years and am familiar with standard audit procedures as well as with the protocols developed by the International Cyanide Management Institute for implementation of the Code.

Signed	Name	Signature	Date
Lead Auditor* and Mining Technical Specialist	Kent Johnejack	Kuthner	May 13, 2015
Mining Technical Specialist	Ivon Aguinaga	Ivon Aguinagas.	May 13, 2015
Independent Auditor	Rick Frechette	la Selette	May 13, 2015

Use additional pages if necessary

State of Arizona)	
County of Pime)	
Subscribed and sworn (or affirmed) before	e me this 13 day 60 , 2015
by Kent Johne iack.	
Notary Public State of Arizona Pirna County Rosina Thorne My Commission Expires 03/03/2016	(Notary Public

^{*}The lead auditor's signature must be certified by notarization or equivalent.