

Auditor Credentials Form



Facility Audited: Transportes Verasay Ltd, Copiapo, Chile **Date:** 24 to 25 July 2013

Lead Auditor Credentials

Lead Auditor: Juan Carlos Rangel Lopez **Auditor Certification Number:** 057

Certifying Organization:

Name: Colegio de Ingenieros Ambientales de México (CINAM) **Telephone:** +52555582 4778

Address: Córdoba 128 Interior 302, Colonia Roma, Mexico D. F. C.P.06700 Mexico.

Web Site Address: www.cinam.org.mx;

Minimum experience: 3 audits in past 7 years as Lead Auditor

Year	Type of Facility, Type of Audit Led	Country & State/Province
2013	Cyanide Code Certification Audit to two additional transport subcontractors for a consigner.	Mexico
2013	Cyanide Code Certification Audit for a gold mine	Nevada, USA
2013	Cyanide Code Gap Analysis for a gold mine	Nicaragua
2013	Cyanide Transportation Audit for a transport company.	Honduras
2013	Cyanide Transportation audit for a consigner.	Honduras
2012	Cyanide Transportation (following the ICMI protocols) for one transport company	Dominican Republic
2012	Cyanide Code Certification Audit for a gold mine in Sonora	Mexico
2012	Cyanide Code Gap Analysis for a gold mine in Sonora	Mexico
2012	Cyanide Code Gap Analysis for a gold mine in Guerrero	Mexico
2012	Cyanide Transportation (following the ICMI protocols) for one transport company (pre-operation audit)	Peru
2012	Cyanide Transportation (following the ICMI protocols) for one transport company	Mexico
2012	Cyanide Transportation (following the ICMI protocols) for one consigner.	Guatemala
2011	Cyanide Transportation (following the ICMI protocols) for one transport company	Chile
2011	Cyanide Code GAP Analysis, Gold Mine	Guatemala
2011	Cyanide Transportation (following the ICMI protocols) for one transport company (pre-operation audit)	Peru
2011	Cyanide Transportation (following the ICMI protocols) for one consigner.	Argentina
2010	Cyanide Transportation (following the ICMI protocols) for one consigner and one transport company.	Argentina
2010	Cyanide Transportation (following the ICMI protocols) for one consigner and one transport company.	Chile
2010	Cyanide Transportation (following the ICMI protocols) for two consigners and three transport companies.	Peru
2010	Cyanide Transportation (following the ICMI protocols)	Panama
2009	Three hazardous waste disposal sites (Env.)	Tijuana, Baja California, Mexico
2009	Cyanide Transportation (following the ICMI protocols)	Guatemala, Guatemala
2009	Cyanide Transportation (following the ICMI protocols)	San Pedro Sula, Honduras
2008	Detonators manufacturing facility (handles explosive chemicals) (Environmental Audit)	Reynosa, Tamaulipas, Mexico
2008	Locomotives repair shop (EHS)	San Luis Potosi, SLP, Mexico
2008	Locomotives repair shop (EHS)	Torreon, Coahuila, Mexico
2007	High Tech/Telecom (EHS)	Juarez, Chihuahua, Mexico
2006	Aluminum extrusion (Env.)	Guadalajara, Jalisco, Mexico

Cyanide-related Operations Experience

Each auditor must have at least 3 years; at least one auditor must have at least 7 years experience

Auditor	Yrs.	Relevant Position Titles	Types of Operations
Juan Carlos Rangel	16	Project Manager	Environmental Consultant performing and supervising over 700 Phase I Environmental Site Assessments, approximately 25 % of which have been performed in chemical or manufacturing facilities handling hazardous chemicals (e.g. pesticides synthesis, fertilizers, chromium plating, acid production, polymers production, solvent based paint manufacture, solvent and acids purification, manufacture and use of explosives, etc). Over 60 EHS compliance audits; he has been lead auditor in 20, five of them have been to chemical facilities. Over 20 Cyanide Code Audits and Gap Analyses for mines, transport companies and distribution centers.

Statement of No Conflict

I certify that I have not audited any component of this facility for which I was responsible for design or development; nor have I within the past year been an employee of the facility, its parent company, or associated affiliates. Excluding audits, I have not derived more than 30% of my income within the past 5 years from the facility, its parent, or associated affiliates. I have not participated in more than two consecutive Cyanide Code audits of this facility. I have participated in at least 3 health, safety, and/or environmental audits in the past 7 years and am familiar with standard audit procedures as well as with the protocols developed by the International Cyanide Management Institute for implementation of the Code.

Signed,
Lead Auditor*

Name
Juan Carlos Rangel

Signature

Date
25 July 2013

*The lead auditor's signature must be certified by notarization or equivalent.



----- CARLOS ALEJANDRO DURÁN LOERA, TITULAR DE LA NOTARIA NÚMERO
ONCE DEL DISTRITO FEDERAL, CERTIFICO: QUE ANTE MÍ, RECONOCIÓ SU FIRMA EN
EL PRESENTE DOCUMENTO Y RATIFICÓ EL CONTENIDO DEL MISMO PARA TODOS SUS
EFECTOS LEGALES, EL SEÑOR JUAN CARLOS RANGEL LÓPEZ; DE CUYA COMPROBACIÓN
DE FIRMA, LEVANTÉ EN EL PROTOCOLO DE LA NOTARIA A MI CARGO, EL ACTA
MARCADA CON EL NÚMERO **SESENTA Y DOS MIL OCHOCIENTOS DIECIOCHO**, DE ESTA
MISMA FECHA Y COMO LO DISPONE EL ARTÍCULO CIENTO TREINTA Y CINCO DE LA
LEY DEL NOTARIADO EN VIGOR EL CITADO COMPARECIENTE ESTAMPA SU HUELLA
DIGITAL, ESCRIBE DE SU PUÑO Y LETRA SU NOMBRE, APELLIDOS Y FIRMA EL ACTA
ANTES RELACIONADA. -----

----- DISTRITO FEDERAL, MÉXICO A DIECINUEVE DE SEPTIEMBRE DEL AÑO
DOS MIL TRECE.-----

EL/emv

44305

LIC. CARLOS ALEJANDRO DURÁN LOERA
TITULAR DE LA NOTARIA 11 DEL DF

