



### Auditor Credentials Form

Aura Minerals Inc.  
San Andres Mine  
Certification Audit  
15-19 April 2013 and 20-24 August 2013

**Facility Audited:** San Andres Mine

**Date:** 29 January 2014

#### Lead Auditor Credentials

Lead Auditor: Dr. Andrew Gillam, PGeo

Auditor Certification Number: EP(CEA) 21246

#### Certifying Organization Name

ECO Canada/CECAB

Address: Suite 200, 308-11th Ave SE,  
Calgary, AB T2G 0Y2

Telephone Number:

+1 (403) 233-7484

Web Site Address:

[www.cecab.org](http://www.cecab.org)

#### Audit Experience Summary

Minimum experience: 3 audits in past 7 years as Lead Auditor

Year	Type of Facility, Type of Audit Led	Country & State/Province
2013	Gold Mining Operation, Cyanide Code Internal Audit	Honduras, Copan
2013	Oil Sands Mining Operation, Environmental and Health and Safety Audit	Canada, Alberta
2013	Gold Mining Operation, Cyanide Code Audit	Azerbaijan, Gedabek
2012	Gold Mining Operation, Cyanide Code Internal Audit	Azerbaijan, Gedabek
2012	Gold Mining Operation, Cyanide Code Internal Audit and Occupational Health and Safety Audit	Kyrgyzstan, Chaarat
2011	Agricultural Product Processing, Greenhouse Gas (GHG) Verification Audit	Canada, Ontario
2010	Gold Mining Operation, Cyanide Code Internal Audit	Honduras, Copan



Year	Type of Facility, Type of Audit Led	Country & State/Province
2010	Airport Operation, Environmental Management System (EMS) and Occupational Health and Safety Management System (OHSMS) Audit	Canada, Alberta
2010	National Airline Operations, GHG Verification Audit	Canada, Ontario
2009	National Railway Operations, GHG Verification Audit	Canada, Ontario
2008	Hydroelectric facilities, EMS and OHSMS Audit	Canada, British Columbia
2008	Federal Government, EMS and OHSMS Audit	Canada, National
2007	Metal Smelting, EMS Audit	Canada, British Columbia
2007	Wood Processing Operating EMS/Chain of Custody (CoC) Audit	United States/Oregon
2007	Coal-fired Power Station. EMS Audit	Canada, Alberta
2007	Wood Processing Operation, EMS/CoC Audit	United States, Mississippi
2007	Wood Processing Operation, EMS/CoC Audit	Canada, New Brunswick

### Cyanide-related Operations Experience

Each auditor must have at least 3 years; at least one auditor must have at least 7 years experience

Auditor	Yrs	Relevant Position Titles	Types of Operations
Dr. Andrew Gillam	11	Geochemist, EHS Consultant and Auditor	<p>Gold Mining and Use of Cyanide (&gt;20% of time):</p> <ul style="list-style-type: none"> <li>• Aura Minerals – San Andres, HN</li> <li>• AIMC – Gedabek, AZ</li> <li>• Chaarat Gold – Chaarat, KG</li> <li>• Rio Tinto – Oyu Tolgoi, MN</li> <li>• Gabriel Resources – Rosa Montana</li> <li>• Barrick Gold – Petaquilla, PA</li> <li>• Placer Dome – Global Operations</li> </ul> <p>Chemical production (explosives and polymers), postgraduate research, university lecturer, and analytical laboratory.</p>


**Statement of No Conflict**

I certify that I have not audited any component of this facility for which I was responsible for design or development; nor have I within the past year been an employee of the facility, its parent company, or associated affiliates.

Excluding audits, I have not derived more than 30% of my income within the past 5 years from the facility, its parent, or associated affiliates.

I have not participated in more than two consecutive Cyanide Code audits of this facility. I have participated in at least 3 health, safety, and/or environmental audits in the past 7 years and am familiar with standard audit procedures as well as with the protocols developed by the International Cyanide Management Institute for implementation of the Code.

Signed,

	Name	Signature	Date
Lead Auditor*	Andrew Gillam, MBA, PhD, PGeo, EP(CEA)		29 January 2014

\* Witnessed:

Signed before me at:

Kuwait City, Kuwait, *30 January 2014*

By:

Andrew Gillam

29 January 2014

  
Canadian Consular Section, Kuwait City, Kuwait  
