

## Auditor Credentials Form


**Facility Audited:** Sunrise Dam Gold Mine  
Western Australia, Australia

**Date:** March 4, 2007

<b>Lead Auditor Credentials</b>	
Lead Auditor: Mark Thompson	Auditor Certification Number: 014080
Certifying Organization: Name: RABQSA	Telephone Number.: +61 2 4728 4600
	Address: PO Box 347, Penrith, NSW Australia 2750 Web Site Address:
	<a href="http://www.rabqsa.com">www.rabqsa.com</a>

Year	Type of Facility, Type of Audit Led	Country & State/Province
2002 and 2003	Internal Cyanide Audit – gold mining operations for major industry producer – 8 in total	Western Australia, Queensland and Northern Territory, Australia and New Zealand
2004	Gold Mining Operations, draft International Cyanide Management Code gap analysis – 8 in total	Tasmania, Queensland, Western Australia, Australia Enga Province, Papua New Guinea Mara District, Tanzania
2005	Gold and Copper Mining operations – Environmental Management Systems including cyanide management – 3 in total	Western Australia and Northern Territory, Australia Sumbawa, Indonesia
2006	Gold and Copper Mining operations – Environmental Management Systems including cyanide management – total 3 to date	Western Australia and Northern Territory, Australia Sumbawa Indonesia
	Gold Mining Operations, International Cyanide Management Code gap analysis	New Ireland Province, Papua New Guinea
	Cyanide Transport, International Cyanide Management Code Certification Audit	Western Australia, Australia

AngloGold Ashanti  
Sunrise Dam Gold Mine

  
 Signature of Lead Auditor

March 4, 2007

## Auditor Credentials Form - continued

<b>Cyanide-Related Operations Experience</b>			
Auditor	Years	Relevant Position Titles	Types of Operations
Mark Thompson (lead)	10	Consultant Engineer – mine waste disposal including tailings dam investigation, design and construction	Various gold mining operations, Australia and Papua New Guinea
	4	Senior Engineer and Acting Chief Engineering	Porgera Gold Mine, Papua New Guinea
	10	Principal Consultant – risk assessment facilitation, audits and reviews including tailings dams (operating and closure) and dangerous goods transportation (cyanide and other reagents)  Engineering design, construction and closure review for tailings dams, water management and related infrastructure	Various gold mining operations located within Australia, New Zealand, Papua New Guinea, Indonesia, Tanzania and USA.
Raymond L. Biehl (technical specialist)	11	Operation and project metallurgist– various operations	Gold mining operations, Western Australia
	13	Mill Process Superintendent – various operations	Gold mining operations, Western Australia and Papua New Guinea
	4	Mill Process Manager	Gold mining operation, Indonesia
	3	Principals Representative – Ore Treatment / Manager Ore Processing	Major gold mine design, construction and commissioning, Western Australia
R. John McKenna (technical specialist)	2	Consulting Scientist – cyanide code gap analysis audits (5), assay laboratory setup and audits, occupational hygiene survey, NATA auditor	Various gold and coal mining operations, Australia, Papua New Guinea and Tanzania
	14	Chief Scientist and Chief Chemist – occupational hygienist, cyanide code team leader, various process projects and research, assay laboratory management and accreditation, dangerous goods control, NATA auditor.	Porgera Gold Mine, Papua New Guinea
	5	Superintendent, Occupational Hygiene and Environmental Chemistry	Bougainville Copper Ltd., Papua New Guinea
	7	Associate Professor, Department of Chemical Technology	University of Technology, PNG.

AngloGold Ashanti  
Sunrise Dam Gold Mine




  
Signature of Lead Auditor

March 4, 2007

## Auditor Credentials Form – continued

### Statement of No Conflict

I certify that I have not audited any component of this facility for which I was responsible for design or development; nor have I within the past year been an employee of the facility, its parent company, or associated affiliates. Excluding audits, I have not derived more than 30% of my income within the past 5 years from the facility, its parent, or associated affiliates. I have not participated in more than two consecutive Cyanide Code audits of this facility. I have participated in at least 3 health, safety, and/or environmental audits, inspections or reviews in the past 7 years and am familiar with standard audit procedures as well as with the protocols developed by the International Cyanide Management Institute for implementation of the Code.

Auditor	Name	Signature	Date
Lead Auditor	Mark Thompson		March 4, 2007
Auditor 1	Raymond L. Biehl		March 4, 2007
Auditor 2	R. John McKenna		March 4, 2007

Signature of Declarant:  .....


Declared at: Lihir, Papua New Guinea .....

This 6<sup>th</sup> day of March 2007

Before me:  .....

**A. BAKEN**  
 Signature and title of the person before whom the declarant has made

AngloGold Ashanti  
 Sunrise Dam Gold Mine

  
 Signature of Lead Auditor

March 4, 2007