

INTERNATIONAL CYANIDE MANAGEMENT INSTITUTE

Auditor Credentials Form

Facility Audited: Transwood Inc., Nevada

Date: September 14, 2006

Lead Auditor and Technical Expert Credentials

Lead Auditor: Scott H. Miller, P.G., CEA
 Golder Associates Inc.
 44 Union Blvd., Suite 300
 Lakewood, CO 80228

Auditor Certification Number: 9752
 Telephone Number: (303) 980-0540

Certifying Organization: National Registry of Environmental
 Professionals (NREP)

Telephone Number.: (847) 724-6631

Address: PO Box 2099, Glenview, IL 60025

Web Site Address: www.nrep.org

Minimum experience: 3 audits in past 7 years as Lead Auditor

Year	Type of Facility, Type of Audit Led	Country & State/Province
2006	Confidential gold cyanide heap leach facility – Lead Auditor for Gap analysis and verification audit for compliance with the ICMC. Audit followed ICMI verification protocol and included development of detailed audit report and action plan.	Nevada, USA
2002-2006	United Park City Mines Company - Historic mining and milling complex including two CERCLIS sites and 14 mine/mill sites; lead auditor for comprehensive environmental compliance audit and liability cost assessment. Original audit and liability assessment report delivered December 2002, since then have completed quarterly compliance audits including interviews, review of new documents and remediation progress, site visits and reporting.	Utah, USA
2005	Confidential gold cyanide heap leach facility - Environmental compliance audit and due diligence for stock purchase of company, including interviews, record review, and permit compliance. Compliance issues identified and corrective action plans and cost estimates developed.	Nevada, USA
1997-2006	Climax Mine - Remediated mill tailings impoundment; Comprehensive 3 rd -party environmental compliance audit during and post-remediation for conversion of impoundment for water storage reservoir on Eagle River. Ongoing annual audits of facility include interviews, document review, site visits, water quality compliance verification sampling and reporting.	Colorado, USA
2001	Ruby Hill Mine - Gold cyanide heap leach facility; Compliance audit of mine closure plan including cyanide facility closure and cost estimate.	Nevada, USA
1999	ZCCM - Copper-cobalt mine and mill complex; Compliance audit of facility against World Bank compliance criteria.	Konkola, Zambia


Cyanide-related Operations Experience

Each auditor must have at least 3 years; at least one auditor must have at least 7 years experience

Auditor	Yrs.	Relevant Position Titles	Types of Operations
Scott H. Miller, CEA	15	Mining Environmental Consultant	Since 1991, Mr. Miller has provided environmental consulting services for the mining industry. Approximately 75% of his time has been spent with gold operations including geologic and geochemical site characterizations, new mine operating plans, mine permitting, compliance auditing, remediation plans, water management plans, cyanide facility closure plans, closure cost assessment, and water quality compliance management.

Statement of No Conflict

I certify that I have not audited any component of this facility for which I was responsible for design or development; nor have I within the past year been an employee of the facility, its parent company, or associated affiliates. Excluding audits, I have not derived more than 30% of my income within the past 5 years from the facility, its parent, or associated affiliates. I have not participated in more than two consecutive Cyanide Code audits of this facility. I have participated in at least 3 health, safety, and/or environmental audits in the past 7 years and am familiar with standard audit procedures as well as with the protocols developed by the International Cyanide Management Institute for implementation of the Code.

Signed	<u>Name</u>	<u>Signature</u>	<u>Date</u>
Lead Auditor*	Scott H. Miller, CEA		9/15/06
Auditor 1			
Auditor 2			
Auditor 3			
Auditor 4			



Use additional pages if necessary

*The lead auditor's signature must be certified by notarization or equivalent.

Kathy Jeffery
 State of Colorado
 Jefferson County
 12/28/06

INTERNATIONAL CYANIDE MANAGEMENT INSTITUTE

Auditor Credentials Form

Facility Audited: TransWood Inc., Nevada

Date: September 14, 2006

Technical Expert Credentials

Transportation Auditor: Karen Olson
Golder Associates Inc.
44 Union Blvd., Suite 300
Lakewood, CO 80228
Certifying Organization:
Address:

Auditor Certification Number:
Telephone Number (303) 980-0540

Telephone Number:
Web Site Address:

Minimum experience: 3 audits in past 7 years as Lead Auditor

Year	Type of Facility, Type of Audit Led	Country & State/Province
2001-2005	Department of Energy – Nuclear weapons production and clean-up site. Auditor for the verification that hazardous/radioactive waste packages meet the requirements established by federal and state governments, to include RCRA permitting, Department of Transportation, TSDF's and the DOE.	Golden, Colorado, USA
1998-2000	Department of Energy – Nuclear weapons production and clean-up site. Audited Beryllium Program. Ensured that all Beryllium areas were properly posted, employee training was current and complete, and all proper working practices were correctly followed.	Golden, Colorado, USA
1993-1998	Department of Energy – Nuclear weapons production and clean-up site. Decontaminations Facilities Supervisor of RCRA unit 18.01. Performed bi-yearly audits for the client to ensure that the facility was with the parameters of the RCRA permit.	Golden, Colorado, USA


Cyanide-related Operations Experience

Each auditor must have at least 3 years; at least one auditor must have at least 7 years experience

Auditor	Yrs.	Relevant Position Titles	Types of Operations
D. Karen Olson	12	Environmental compliance, handling and shipment of hazardous/radiological materials and waste.	Since 1993, Ms. Olson has provided a variety of services to the Department of Energy. Approximately 50% of her time has been spent with the safe transportation of hazardous/radioactive materials and waste. She has taken and passed the Department of
			Transportation advanced training classes: Transportation of Hazardous Materials, Transportation of Mixed Materials, and Transportation of Radioactive Materials.

Statement of No Conflict

I certify that I have not audited any component of this facility for which I was responsible for design or development; nor have I within the past year been an employee of the facility, its parent company, or associated affiliates. Excluding audits, I have not derived more than 30% of my income within the past 5 years from the facility, its parent, or associated affiliates. I have not participated in more than two consecutive Cyanide Code audits of this facility. I have participated in at least 3 health, safety, and/or environmental audits in the past 7 years and am familiar with standard audit procedures as well as with the protocols developed by the International Cyanide Management Institute for implementation of the Code.

Signed,	<u>Name</u>	<u>Signature</u>	<u>Date</u>
Lead Auditor*	Karen Olson		9/14/06
Auditor 1			
Auditor 2			
Auditor 3			
Auditor 4			

Use additional pages if necessary

*The lead auditor's signature must be certified by notarization or equivalent.