

INTERNATIONAL CYANIDE MANAGEMENT INSTITUTE

Auditor Credentials Form

For The International Cyanide Management Code

www.cyanidecode.org

July 2005

The International Cyanide Management Code (hereinafter "the Code"), this document, and other documents or information sources referenced at www.cyanidecode.org are believed to be reliable and were prepared in good faith from information reasonably available to the drafters. However, no guarantee is made as to the accuracy or completeness of any of these other documents or information sources. No guarantee is made in connection with the application of the Code, the additional documents available or the referenced materials to prevent hazards, accidents, incidents, or injury to employees and/or members of the public at any specific site where gold is extracted from ore by the cyanidation process. Compliance with this Code is not intended to and does not replace, contravene or otherwise alter the requirements of any specific national, state or local governmental statutes, laws, regulations, ordinances, or other requirements regarding the matters included herein. Compliance with this Code is entirely voluntary and is neither intended nor does it create, establish, or recognize any legally enforceable obligations or rights on the part of its signatories, supporters or any other parties.

Auditor Credentials Form Facility Audited: Pierina Gold Mine, Peru Date: 27/09/10 - 30/09/10

Lead Auditor Credentials

Lead Auditor: Alistair Cadden

Auditor Certification Number: 12619

Certifying Organization: Institute of Environmental Management and Assessment (IEMA)

Telephone Number.:+44 1522 54009

Address: St Nicholas House, 70 Newport, Lincoln, LN1 3DP, UK Web Site Address: www.iema.net

Minimum experience: 3 Audits in past 7 years as Lead Auditor

Year	Type of Facility, Type of Audit Led	Country & State/Province	
2002	Sotkamo talc mine; cyanide management and tailings dam safety	Kajaani, Finland	
2003	Trepca mines, tailings dam safety audits	Mitrovica, Kosovo	
	Lega Dembi Gold Mine, tailings dam safety and cyanide management	Shakisso, Ethiopia	
	Ovacik Gold Mine; cyanidation process and tailings dam safety	Izmir, Turkey	
	Jilau Gold Mine audits of health and safety systems, cyanide management, emergency response planning, tailings dam safety and environmental management	Penjikent, Tajikistan	
2004	Rosia Poieni Mine, Safety audit of copper mine	Abrud, Romania	
2005	Jilau Gold Mine; audits of environmental management, health and safety management, tailings dam safety and cyanide management	Penjikent, Tajikistan	
2006	Lega Dembi Gold Mine, tailings dam safety and cyanide management	Shakisso, Ethiopia	
2007	Lichkvaz Tey Gold Mine health and safety audit	Meghri, Armenia	
2008	Lega Dembi Gold Mine, tailings dam safety and cyanide management	Shakisso Ethiopia	
2008	Tulawaka Gold Mine, ICMI Cyanide code compliance audit	Tulawaka, Tanzania	
2008	Bulyanhulu Gold Mine, ICMI Cyanide code compliance audit	Bulyanhulu, Tanzania	
2009	Pokrovskiy Gold Mine, ICMI Gap Analysis audit	Amur Oblast, Russian Federation	
2009	Pioneer Gold Mine, ICMI Gap Analysis audit	Amur Oblast, Russian Federation	
2009	Porcupine Gold Mines gap analysis audit	Timmins, Ontario, Canada	
2009	Red Lake Gold Mines gap analysis audit	Red Lake, Ontario, Canada	
2010	Porcupine Gold Mines ICMI cyanide code compliance audit	Timmins, Ontario, Canada	
2010	Red Lake Gold Mines ICMI cyanide code compliance audit	Red Lake, Ontario, Canada	

Cyanide-related Operations Experience

Each auditor must have at least 3 years; at least one auditor must have at least 7 years experience

Auditor	Yrs.	Relevant Position Titles	Types of Operations
Alistair Cadden	16	Principal, Geotechnical Engineer	CIL/CIP/RIP plants; Heap Leach Operations Base metals flotation plants
Sophie Wheeler	14	Environmental Auditor	Manufacturing, mining and waste facilities.
Ivon Aguinaga	9	Civil Engineer	CIL/CIP/RIP plants; Heap Leach Operations Base metals flotation plants

Statement of No Conflict

I certify that I have not audited any component of this facility for which I was responsible for design or development; nor have I within the past year been an employee of the facility, its parent company, or associated affiliates. Excluding audits, I have not derived more than 30% of my income within the past 5 years from the facility, its parent, or associated affiliates. I have not participated in more than two consecutive Cyanide Code audits of this facility. I have participated in at least 3 health, safety, and/or environmental audits in the past 7 years and am familiar with standard audit procedures as well as with the protocols developed by the International Cyanide Management Institute for implementation of the Code.

Signed	Name	Signature	Date
Lead Auditor*	Alistair Cadden	Hotar Caldu	9th Feb 2011
Auditor 1	Sophie Wheeler	Scheele.	9th Feb 2011
Auditor 2	Ivon Aguinaga	Ivan Aguinagas	9K Feb 2011

Certify that I was present and saw

Soffie Wheley Alex the above named sign this document at 33 Queen Street, Maidenhead, Berks. U.K.

this day of Mary 20.1/ Adrian Peter Mark Watney

Notary Public July meltored