

Auditor Credentials Form

Facility Audited: Gold Fields St Ives Gold Mine, Australia

Date: 8th – 12th September 2008

Lead Auditor Credentials

Lead Auditor: Arend Hoogervorst

Eagle Environmental

Private Bag X06

KLOOF 3640, South Africa

Email: arend@eagleenv.co.za

Tel:- +27 31 7670244

Fax:- +27 31 7670295

Website: www.eagleenv.co.za

Certifying Organization: Name: RABQSA International

Telephone Number.: +61 2 4728 4600

Address: P O Box 347, Penrith BC, NSW 2751, Australia

Web Site Address: www.rabqsa.com

Auditor Certification Number: 022609

Minimum experience: 3 audits in past 7 years as Lead Auditor

Year	Type of Facility, Type of Audit Led	Country & State/Province
1991 to 2007 – 114 audits (Audit logs held by RABQSA & ICMI)	Chemicals, manufacturing, oil and gas, mining (gold, coal, chrome), foods, and heavy industry sectors. EMS, Compliance, Environmental Due Diligence, HSEC, SHE audits. Lead Auditor in 84 audits.	South Africa, Botswana, Mozambique, Mali, Namibia, Ghana
2006	ICMI Cyanide Code Compliance Audits: Lead Auditor *Sasol Polymers Cyanide Plants 1 & 2 and Storage Areas (Production) *Sasol SiLog (Transportation) ICMI Cyanide Code Gap Analyses: Lead Auditor *AngloGold Ashanti West Gold Plant *AngloGold Ashanti East Gold Acid Float Plant *AngloGold Ashanti Noligwa Gold Plant *AngloGold Ashanti Kopanang Gold Plant *AngloGold Ashanti Savuka Gold Plant *AngloGold Ashanti Mponeng Gold Plant	South Africa South Africa South Africa South Africa South Africa South Africa South Africa South Africa
2007	ICMI Cyanide Code Compliance Audits: Lead Auditor *AngloGold Ashanti West Gold Plant *AngloGold Ashanti East Gold Acid Float Plant *AngloGold Ashanti Noligwa Gold Plant *AngloGold Ashanti Kopanang Gold Plant *AngloGold Ashanti Savuka Gold Plant	South Africa South Africa South Africa South Africa South Africa

2007	<p>*AngloGold Ashanti Mponeng Gold Plant</p> <p>ICMI Cyanide Code Gap Analyses: Lead Auditor</p> <p>*Goldfields Tarkwa Gold Mine *Goldfields Abusso Damang Mine *Goldfields South Deep Gold Mine *Goldfields Beatrix 1 Gold Mine *Goldfields Beatrix 2 Gold Mine *Goldfields Driefontein No 1 Gold Mine *Goldfields Kloof No 1 Gold Mine *Goldfields Kloof No 2 Gold Mine *Goldfields Driefontein No 2 Gold Mine *Goldfields Driefontein No 3 Gold Mine *Goldfields St Ives Gold Mine *Goldfields Agnew Gold Mine *Harmony No 1 Gold Plant *AngloGold Ashanti Africa – Morila Gold Mine *AngloGold Ashanti Africa – Sadiola & Yatela Gold Mines</p>	<p>South Africa</p> <p>Ghana Ghana South Africa South Africa South Africa South Africa South Africa South Africa South Africa South Africa Australia Australia South Africa Mali Mali</p>
2008	<p>ICMI Cyanide Code Compliance Audits: Lead Auditor</p> <p>*Goldfields Tarkwa Gold Mine *Goldfields Abusso Damang Mine *Vehrad Transport & Haulage *Goldfields South Deep Gold Mine *Goldfields Beatrix 2 Gold Mine *Goldfields Beatrix 1 Gold Mine *Goldfields Driefontein 1 Gold Mine *Goldfields Driefontein 2 Gold Mine *Goldfields Driefontein 3 Gold Mine</p>	<p>Ghana Ghana Ghana South Africa South Africa South Africa South Africa South Africa South Africa</p>
2008	<p>ICMI Cyanide Code Gap Analyses: Lead Auditor</p> <p>*AngloGold Ashanti Africa – Navachab Gold Mine *AngloGold Ashanti Africa – Gaita Gold Mine *Harmony Doornkop Gold Mine *AngloGold Ashanti Africa – Iduapriem Gold Mine *AngloGold Ashanti Africa – Siguiri Gold Mine *Harmony Central Gold Mine *Harmony Kalgold Gold Mine *Harmony Evander Gold Mine</p>	<p>Namibia Tanzania South Africa Ghana Guinea South Africa South Africa South Africa</p>

Cyanide-related Operations Experience

Each auditor must have at least 3 years; at least one auditor must have at least 7 years experience

Auditor	Yrs.	Relevant Position Titles	Types of Operations
Dawid M L Viljoen	2008	ICMI Cyanide Code Compliance Audits: Technical Auditor *Goldfields Tarkwa Gold Mine *Goldfields Abusso Damang Mine * Goldfields South Deep Gold Mine * Goldfields Beatrix 2 Gold Mine * Goldfields Beatrix 1 Gold Mine *Goldfields Driefontein 1 Gold Mine *Goldfields Driefontein 2 Gold Mine *Goldfields Driefontein 3 Gold Mine	Ghana Ghana South Africa South Africa South Africa South Africa South Africa South Africa
	2008	ICMI Cyanide Code Gap Analyses: Technical Auditor *AngloGold Ashanti Africa – Navachab Gold Mine *AngloGold Ashanti Africa – Gaita Gold Mine *Harmony Doornkop Gold Mine *AngloGold Ashanti Africa – Iduapriem Gold Mine *AngloGold Ashanti Africa – Siguiri Gold Mine *Harmony Central Gold Mine *Harmony Kalgold Gold Mine *Harmony Evander Gold Mine	Namibia Tanzania South Africa Ghana Guinea South Africa South Africa South Africa
	2007	ICMI Cyanide Code Compliance Audits: Technical Auditor *AngloGold Ashanti West Gold Plant *AngloGold Ashanti East Gold Acid Float Plant *AngloGold Ashanti Noligwa Gold Plant *AngloGold Ashanti Kopanang Gold Plant *AngloGold Ashanti Savuka Gold Plant *AngloGold Ashanti Mponeng Gold Plant	South Africa South Africa South Africa South Africa South Africa South Africa
	2007	ICMI Cyanide Code Gap Analyses: Technical Auditor *Goldfields Tarkwa Gold Mine *Goldfields Abusso Damang Mine *Goldfields South Deep Gold Mine *Goldfields Beatrix 1 Gold Mine *Goldfields Beatrix 2 Gold Mine *Goldfields Driefontein No 1 Gold Mine *Goldfields Kloof No 1 Gold Mine	Ghana Ghana South Africa South Africa South Africa South Africa South Africa

		*Goldfields Kloof No 2 Gold Mine	South Africa
		*Goldfields Driefontein No 2 Gold Mine	South Africa
		*Goldfields Driefontein No 3 Gold Mine	South Africa
		*Goldfields St Ives Gold Mine	Australia
		*Goldfields Agnew Gold Mine	Australia
		* Harmony No 1 Gold Plant	South Africa
		*AngloGold Ashanti Africa – Morila Gold Mine	Mali
		* AngloGold Ashanti Africa – Sadiola & Yatela Gold Mines	Mali
	2006	*AngloGold Ashanti West Gold Plant	South Africa
		*AngloGold Ashanti East Gold Acid Float Plant	South Africa
		*AngloGold Ashanti Noligwa Gold Plant	South Africa
		*AngloGold Ashanti Kopanang Gold Plant	South Africa
		*AngloGold Ashanti Savuka Gold Plant	South Africa
		*AngloGold Ashanti Mponeng Gold Plant	South Africa
	2000 to 2007	Managing Member Afritech Technical and Management services	Conducted various cyanide audits internationally, gold plant designs, Poly metallic designs, competent persons reports.
	1997 - 2000	Manager: AngloGold Ashanti Metallurgical Technical Services	Gold, uranium and floatation technical, technology and planning services
	1995 - 1997	Metallurgical Manager: Vaal Reefs Exploration and Mining Company	Responsible for project management gold and uranium, strategic planning, environmental management, production of gold and uranium plants, gold mine
	1990 - 1995	Project Metallurgist: Vaal Reefs Exploration and Mining Company Projects	Metallurgical gold technical auditing and Uranium strategy and marketing, project management
	1987 - 1990	Plant Manager: Vaal Reef Exploration and Mining Company	Gold and uranium plant general management.
	1980-1985	Production Superintendent Anglo American	Gold and uranium plant production management

	1977 - 1980	Snr Plant Metallurgist – Anglo American	Diamonds with De Beers, gold, uranium, sulphuric acid and slimes deposition sections.
--	-------------------	---	---

Statement of No Conflict

I certify that I have not audited any component of this facility for which I was responsible for design or development; nor have I within the past year been an employee of the facility, its parent company, or associated affiliates. Excluding audits, I have not derived more than 30% of my income within the past 5 years from the facility, its parent, or associated affiliates. I have not participated in more than two consecutive Cyanide Code audits of this facility. I have participated in at least 3 health, safety, and/or environmental audits in the past 7 years and am familiar with standard audit procedures as well as with the protocols developed by the International Cyanide Management Institute for implementation of the Code.

Signed,


Name

Signature

Date


Lead Auditor*

Arend Hoogervorst




30/4/09

Notarized/certified



Auditor

Dawid L Viljoen



BEVERLEY MYRTLE NEL

Conveyancing Paralegal
Ewing McKeown Inc.
(Formerly Ewing Adams & Associates)
Commissioner of Oaths RSA
28 Old Main Road, Hillcrest 3610
REF: 9/1/8/2 Pinetown, 18/11/2004

Date

Use additional pages if necessary

*The lead auditor's signature must be certified by notarization or equivalent.