

Auditor Credentials Form

Facility Audited: AngloGold Ashanti Sadiola Gold Mine, Mali

Date: 3rd – 7th November 2008

Lead Auditor Credentials

Lead Auditor: Arend Hoogervorst
Eagle Environmental
Private Bag X06
KLOOF 3640, South Africa

Email: arend@eagleenv.co.za
Tel:- +27 31 7670244
Fax:- +27 31 7670295
Website: www.eagleenv.co.za

Certifying Organization: Name: RABQSA International
Telephone Number.: +61 2 4728 4600
Address: P O Box 347, Penrith BC, NSW 2751, Australia
Web Site Address: www.rabqsa.com

Auditor Certification Number: 022609

Minimum experience: 3 audits in past 7 years as Lead Auditor

Year	Type of Facility, Type of Audit Led	Country & State/Province
1991 to 2007 – 114 audits (Audit logs held by RABQSA & ICMI)	Chemicals, manufacturing, oil and gas, mining (gold, coal, chrome), foods, and heavy industry sectors. EMS, Compliance, Environmental Due Diligence, HSEC, SHE audits. Lead Auditor in 84 audits.	South Africa, Botswana, Mozambique, Mali, Namibia, Ghana
2006	ICMI Cyanide Code Compliance Audits: Lead Auditor *Sasol Polymers Cyanide Plants 1 & 2 and Storage Areas (Production) *Sasol SiLog (Transportation) ICMI Cyanide Code Gap Analyses: Lead Auditor *AngloGold Ashanti West Gold Plant *AngloGold Ashanti East Gold Acid Float Plant *AngloGold Ashanti Noligwa Gold Plant *AngloGold Ashanti Kopanang Gold Plant *AngloGold Ashanti Savuka Gold Plant *AngloGold Ashanti Mponeng Gold Plant	South Africa South Africa South Africa South Africa South Africa South Africa South Africa South Africa
2007	ICMI Cyanide Code Compliance Audits: Lead Auditor *AngloGold Ashanti West Gold Plant *AngloGold Ashanti East Gold Acid Float Plant *AngloGold Ashanti Noligwa Gold Plant *AngloGold Ashanti Kopanang Gold Plant *AngloGold Ashanti Savuka Gold Plant	South Africa South Africa South Africa South Africa South Africa

2007	*AngloGold Ashanti Mponeng Gold Plant	South Africa
	ICMI Cyanide Code Gap Analyses:	
	Lead Auditor	
	*Goldfields Tarkwa Gold Mine	Ghana
	*Goldfields Abusso Damang Mine	Ghana
	*Goldfields South Deep Gold Mine	South Africa
	*Goldfields Beatrix 1 Gold Mine	South Africa
	*Goldfields Beatrix 2 Gold Mine	South Africa
	*Goldfields Driefontein No 1 Gold Mine	South Africa
	*Goldfields Kloof No 1 Gold Mine	South Africa
	*Goldfields Kloof No 2 Gold Mine	South Africa
	*Goldfields Driefontein No 2 Gold Mine	South Africa
	*Goldfields Driefontein No 3 Gold Mine	South Africa
	*Goldfields St Ives Gold Mine	Australia
	*Goldfields Agnew Gold Mine	Australia
2008	*Harmony No 1 Gold Plant	South Africa
	*AngloGold Ashanti Africa – Morila Gold Mine	Mali
	*AngloGold Ashanti Africa – Sadiola & Yatela Gold Mines	Mali
	ICMI Cyanide Code Compliance Audits: Lead Auditor	
	*Goldfields Tarkwa Gold Mine	Ghana
	*Goldfields Abusso Damang Mine	Ghana
	*Vehrad Transport & Haulage	Ghana
	*Goldfields South Deep Gold Mine	South Africa
	*Goldfields Beatrix 2 Gold Mine	South Africa
	*Goldfields Beatrix 1 Gold Mine	South Africa
	*Goldfields Driefontein 1 Gold Mine	South Africa
	*Goldfields Driefontein 2 Gold Mine	South Africa
	*Goldfields Driefontein 3 Gold Mine	South Africa
	*Goldfields St Ives Gold Mine	Australia
	*Goldfields Agnew Gold Mine	Australia
	*Goldfields Kloof 1 Gold Mine	South Africa
	*Goldfields Kloof 2 Gold Mine	South Africa
	*AngloGold Ashanti Africa – Siguiri Gold Mine	Guinea
	*AngoGold Ashanti Africa – Yatela Gold Mine	Mali
2008	ICMI Cyanide Code Gap Analyses:	
	Lead Auditor	
	*AngloGold Ashanti Africa – Navachab Gold Mine	Namibia
	*AngloGold Ashanti Africa – Gaita Gold Mine	Tanzania
	*Harmony Doornkop Gold Mine	South Africa
	*AngloGold Ashanti Africa – Iduapriem Gold Mine	Ghana
	*AngloGold Ashanti Africa – Siguiri Gold Mine	Guinea
	*Harmony Central Gold Mine	Guinea
	*Harmony Kalgold Gold Mine	South Africa

	*Harmony Evander Gold Mine	South Africa
--	----------------------------	--------------

Cyanide-related Operations Experience

Each auditor must have at least 3 years; at least one auditor must have at least 7 years experience




Auditor	Yrs.	Relevant Position Titles	Types of Operations
Dawid M L Viljoen	2008	ICMI Cyanide Code Compliance Audits: Technical Auditor *Goldfields Tarkwa Gold Mine *Goldfields Abusso Damang Mine * Goldfields South Deep Gold Mine * Goldfields Beatrix 2 Gold Mine * Goldfields Beatrix 1 Gold Mine * Goldfields Driefontein 1 Gold Mine * Goldfields Driefontein 2 Gold Mine * Goldfields Driefontein 3 Gold Mine * Goldfields St Ives Gold Mine * Goldfields Agnew Gold Mine * Goldfields Kloof 1 Gold Mine * Goldfields Kloof 2 Gold Mine * AngloGold Ashanti Africa – Siguiri Gold Mine * AngloGold Ashanti Africa – Yatela Gold Mine	Ghana Ghana South Africa South Africa South Africa South Africa South Africa South Africa Australia Australia South Africa South Africa Guinea Mali
	2008	ICMI Cyanide Code Gap Analyses: Technical Auditor *AngloGold Ashanti Africa – Navachab Gold Mine *AngloGold Ashanti Africa – Gaita Gold Mine *Harmony Doornkop Gold Mine *AngloGold Ashanti Africa – Iduapriem Gold Mine *AngloGold Ashanti Africa – Siguiri Gold Mine *Harmony Central Gold Mine *Harmony Kalgold Gold Mine *Harmony Evander Gold Mine	Namibia Tanzania South Africa Ghana Guinea South Africa South Africa South Africa
	2007	ICMI Cyanide Code Compliance Audits: Technical Auditor *AngloGold Ashanti West Gold Plant *AngloGold Ashanti East Gold Acid Float Plant *AngloGold Ashanti Noligwa Gold Plant *AngloGold Ashanti Kopanang Gold Plant *AngloGold Ashanti Savuka Gold Plant *AngloGold Ashanti Mponeng Gold Plant	South Africa South Africa South Africa South Africa South Africa South Africa


2007	ICMI Cyanide Code Gap Analyses:	
	Technical Auditor	
	*Goldfields Tarkwa Gold Mine	Ghana
	*Goldfields Abusso Damang Mine	Ghana
	*Goldfields South Deep Gold Mine	South Africa
	*Goldfields Beatrix 1 Gold Mine	South Africa
	*Goldfields Beatrix 2 Gold Mine	South Africa
	*Goldfields Driefontein No 1 Gold Mine	South Africa
	*Goldfields Kloof No 1 Gold Mine	South Africa
	*Goldfields Kloof No 2 Gold Mine	South Africa
2006	*Goldfields Driefontein No 2 Gold Mine	South Africa
	*Goldfields Driefontein No 3 Gold Mine	South Africa
	*Goldfields St Ives Gold Mine	Australia
	*Goldfields Agnew Gold Mine	Australia
	*Harmony No 1 Gold Plant	South Africa
	*AngloGold Ashanti Africa – Morila Gold Mine	Mali
	*AngloGold Ashanti Africa – Sadiola & Yatela Gold Mines	Mali
	*AngloGold Ashanti West Gold Plant	South Africa
	*AngloGold Ashanti East Gold Acid Float Plant	South Africa
	*AngloGold Ashanti Noligwa Gold Plant	South Africa
2000 to 2007	*AngloGold Ashanti Kopanang Gold Plant	South Africa
	*AngloGold Ashanti Savuka Gold Plant	South Africa
	*AngloGold Ashanti Mponeng Gold Plant	South Africa
	Managing Member Afritech Technical and Management services	Conducted various cyanide audits internationally, gold plant designs, Poly metallic designs, competent persons reports.
	1997 - 2000	Manager: AngloGold Ashanti Metallurgical Technical Services
	1995 - 1997	Metallurgical Manager: Vaal Reefs Exploration and Mining Company
	1990 -	Project Metallurgist: Vaal Reefs Exploration and Mining Company
		Gold, uranium and floatation technical, technology and planning services
		Responsible for project management gold and uranium, strategic planning, environmental management, production of gold and uranium plants, gold mine
		Metallurgical gold technical auditing and Uranium

	1995	Projects	strategy and marketing, project management
	1987 – 1990	Plant Manager: Vaal Reef Exploration and Mining Company	Gold and uranium plant general management.
	1980- 1985	Production Superintendent Anglo American	Gold and uranium plant production management
	1977 - 1980	Snr Plant Metallurgist – Anglo American	Diamonds with De Beers, gold, uranium, sulphuric acid and slimes deposition sections.

Statement of No Conflict

I certify that I have not audited any component of this facility for which I was responsible for design or development; nor have I within the past year been an employee of the facility, its parent company, or associated affiliates. Excluding audits, I have not derived more than 30% of my income within the past 5 years from the facility, its parent, or associated affiliates. I have not participated in more than two consecutive Cyanide Code audits of this facility. I have participated in at least 3 health, safety, and/or environmental audits in the past 7 years and am familiar with standard audit procedures as well as with the protocols developed by the International Cyanide Management Institute for implementation of the Code.

Signed,	Name	Signature	Date
Lead Auditor*	Arend Hoogervorst		18/9/09
Notarized/ certified			
Auditor	Dawid L Viljoen		Date 21/9/09



Use additional pages if necessary

*The lead auditor's signature must be certified by notarization or equivalent.