INTERNATIONAL CYANIDE MANAGEMENT INSTITUTE

Auditor Credentials Form

Facility Audited: Orica Australia Pty Ltd Yarwun Sodium Cyanide Production Facility

Date: 2 October 2006

Auditor and Technical Specialist Credentials

Auditor:

Edward Clerk

Auditor Certification Number:

020778

Certifying Organisation:

RABOSA International

Telephone Number:

+61 2 4728 4600

Address: Web Site Address:

www.rabqsa.com

Minimum experience: 3 audits in past 7 years as Lead Auditor

Year	Type of Facility, Type of Audit Led	Country & State/Province
2004- 2006	Environment audits at various industrial, commercial and mining sites. Audits incorporated health and safety, training and emergency response elements where appropriate, notably:	Various Australia and Foreign.
	2006 – Copper mine Due Diligence Audit and review of Bankable feasibility Study for Macquarie Bank. Lead Environmental Auditor.	
	2006 – Mineral sands due diligence review. Lead Environmental Auditor.	
	2005 – Manganese mine Due Diligence Audit for Commonwealth Bank. Lead Environmental Auditor.	
	2005 – Fertiliser factory (5) Environmental Due Diligence/Compliance Audit. Lead Environmental Auditor.	
	2004 – Gold mine due diligence audit against Canadian Securities Act – National Instrument 43-101. Lead Environmental Auditor.	
	2004 – Gold mine due diligence audit against Canadian Securities Act – National Instrument 43-101. Lead Environmental Auditor.	
2000-	Gold Mines	Tanzania, East Africa.
2004	Environmental auditing including compliance and system audits. Internal Lead Auditor	
1998- 2000	Nickel / Cobalt Mine and Refining Facility On-site environmental auditing including compliance and system audits. Audits incorporated health and safety issues and emergency response where appropriate. Internal Lead Auditor	Western Australia, Australia.
1996- 1998	Gold Mine On-site environmental auditing including compliance and system audits for operational gold mine. Internal Lead Auditor	Queensland, Australia.

l. bll. 26-10-06

1994- 1996	State Government Environmental Agency Environmental auditing incorporating emergency response and health and safety issues associated with manufacturing, maintenance, waste, chemical processing, construction and minor extractive industries.	Queensland, Australia.
	Lead Auditor	

Cyanide-Related Operations Experience

Each auditor must have at least 3 years; at least one auditor must have at least 7 years experience

Auditor	Yrs.	Relevant Position Titles	Types of Operations
Edward W Clerk, CEnvP	2	Senior Environmental Scientist	Since August 2004, Mr. Clerk has provided environmental consulting services for the mining industry. Approximately 50% of his time has been spent with gold operations including new mine operating plans, mine permitting, compliance auditing, remediation and closure plans, and closure cost assessment.
	6	Environmental Superintendent – Tanzania Environmental coordinator.	Between 1996 to 1998 and 2000 to 2004, Mr. Clerk has provided inhouse environmental management and auditing services to gold mining companies in both Western Australia (Reedy Gold) and Tanzania (Barrick Gold).

Statement of No Conflict

I certify that I have not audited any component of this facility for which I was responsible for design or development; nor have I within the past year been an employee of the facility, its parent company, or associated affiliates. Excluding audits, I have not derived more than 30% of my income within the past 5 years from the facility, its parent, or associated affiliates. I have not participated in more than two consecutive Cyanide Code audits of this facility. I have participated in at least 3 health, safety, and/or environmental audits in the past 7 years and am familiar with standard audit procedures as well as with the protocols developed by the International Cyanide Management Institute for implementation of the Code.

Signed, Name Signature (lll 26-10-06 Lead Auditor* **Edward Clerk** Auditor I Auditor 2

figred or Wen balk Wester Autralia on 26 Octobre 2006

Use additional pages if necessary

*The lead auditor's signature must be certified by notarisation or equival

IAN BARRIE MURIE 16 Emerald Terrace West Perth Western Australia General Public Notary