

INTERNATIONAL CYANIDE MANAGEMENT INSTITUTE

Auditor Credentials Form

Facility Audited: CyPlus Idesa Transloading Terminal and Warehouse, Sonora, México

Date: February 11 to 12, 2019

Auditor and Technical Specialist Credentials:

Lead Auditor: Kent R. Johnejack

Auditor Certification Number: Certified Environmental Auditor No. 35173

Certifying Organization: National Registry of Environmental Professionals (NREP)

Telephone Number: (847) 724-4223

Address: P.O. Box 2099, Glenview, IL, United States of America

Web Site Address: www.nrep.org

Minimum Experience: 3 Audits in past 7 years as Lead Auditor

Year	Type of Facility, Type of Audit Led	Country							
Mining – International Cyanide Management Code Pre-Signatory Services									
(Design Reviews)									
2013	Mining Technical Specialist for Rubicon Phoenix Mine	Ontario, Canada							
2015	Mining Technical Specialist for Newmont Long Canyon Mine	Nevada, USA							
2015	Senior Reviewer for Goldcorp Peñasquito Mine - Pyrite Leach Circuit Expansion	Zacatecas, Mexico							
Mining – International Cyanide Management Code Pre-Certification Audits									
	(Gap Analyses)								
2009	Mining Technical Specialist for Peñoles La Herradura Mine	Sonora, Mexico							
2011	Mining Technical Specialist for Goldcorp Wharf Mine	South Dakota, USA							
2011	Lead Auditor and Mining Technical Specialist for Goldcorp Peñasquito Mine	Zacatecas, Mexico							
2013	Lead Auditor and Mining Technical Specialist for Goldcorp Los Filos Mine	Guerrero, Mexico							
2013	Lead Auditor and Mining Technical Specialist for Newmont Yanacocha Mine	Cajamarca, Peru							
2014	Lead Auditor and Mining Technical Specialist for Newmont Emigrant Mine	Nevada, USA							
2015	Mining Technical Specialist for IAMGold Rosebel Mine	Brokopondo, Surinam							
2015	Lead Auditor and Mining Technical Specialist for Minas de Oro Mulatos Mine	Sonora, Mexico							
2016	Mining Technical Specialist for Peñoles Dynamic Leaching Plant at the La Herradura Mine	Sonora, Mexico							
2018	Lead Auditor and Mining Technical Specialist for Fresnillo San Julian Mine	Chihuahua, Mexico							
	Mining – International Cyanide Management Code Certification Audits								
	(Initial or Recertification)								
2010	Mining Technical Specialist for Newmont Twin Creeks Mine	Nevada, USA							
2010	Mining Technical Specialist for Barrick Lagunas Norte Mine	Santiago de Chuco, Peru							
2011	Mining Technical Specialist for Peñoles La Herradura Mine	Sonora, Mexico							
2011	Mining Technical Specialist for Newmont Yanacocha Mine	Cajamarca, Peru							
2011	Lead Auditor and Mining Technical Specialist for Newmont Phoenix Mine	Nevada, USA							
2012	Lead Auditor and Mining Technical Specialist for Newmont Carlin Mine	Nevada, USA							
2012	Lead Auditor and Mining Technical Specialist for Goldcorp Peñasquito Mine	Zacatecas, Mexico							
2012	Lead Auditor and Mining Technical Specialist for Goldcorp Wharf Mine	South Dakota, USA							
2012	Lead Auditor and Mining Technical Specialist for Minas de Oro Mulatos Mine	Sonora, Mexico							
2013	Lead Auditor and Mining Technical Specialist for Goldcorp Los Filos Mine	Guerrero, Mexico							



RECERTIFICATION AUDIT

Year	Type of Facility, Type of Audit Led	Country					
2013	Lead Auditor and Mining Technical Specialist for Goldcorp Red Lake Gold Mines	Ontario, Canada					
2014	Lead Auditor and Mining Technical Specialist for New Gold Cerro de San Pedro Mine	San Luis Potosi, Mexico					
2014	Lead Auditor and Mining Technical Specialist for Peñoles La Herradura Mine	Sonora, Mexico					
2014	Lead Auditor and Mining Technical Specialist for Newmont Yanacocha Mine	Cajamarca, Peru					
2014	Lead Auditor and Mining Technical Specialist for Goldcorp El Sauzal Mine Chihuahua, Me.						
2014	Lead Auditor and Mining Technical Specialist for Barrick Pueblo Viejo Mine Cotui, Dominic						
2015	Lead Auditor and Mining Technical Specialist for Newmont Phoenix Mine	Nevada, USA					
2015	Lead Auditor and Mining Technical Specialist for Newmont Carlin Mine	Nevada, USA					
2015	Lead Auditor and Mining Technical Specialist for Newmont Emigrant Mine	Nevada, USA					
2015	Lead Auditor and Mining Technical Specialist for Coeur Wharf Mine	South Dakota, USA					
2015	Lead Auditor and Mining Technical Specialist for Kinross Maricunga Mine	Copiapo, Region III, Chile					
2015	Lead Auditor and Mining Technical Specialist for Peñoles Noche Buena Mine	Sonora, Mexico					
2016	Lead Auditor and Mining Technical Specialist for Goldcorp Marlin Mine	Guatemala					
2016	Mining Technical Specialist for Goldcorp Musselwhite Mine	Ontario, Canada					
2016	Lead Auditor and Mining Technical Specialist for Minas de Oro Mulatos Mine	Sonora, Mexico					
2016	Lead Auditor and Mining Technical Specialist for Newmont Lone Tree Mine	Nevada, USA					
2017	Lead Auditor and Mining Technical Specialist for Barrick Goldstrike Mine	Nevada, USA					
2017	Lead Auditor and Mining Technical Specialist for New Gold Cerro de San Pedro Mine	San Luis Potosi, Mexico					
2017	Lead Auditor and Mining Technical Specialist for Agnico Eagle La India Mine	Sonora, Mexico					
2017	Lead Auditor and Mining Technical Specialist for Anglogold Ashanti Cerro Vanguardia Mine Santa Cruz, Arger						
2017	Lead Auditor and Mining Technical Specialist for Barrick Pueblo Viejo Mine	list for Barrick Pueblo Viejo Mine Cotui, Dominican Republic					
2018	Mining Technical Specialist for Gorubso Kardzhali Plant	Kardzhali, Bulgaria					
2019	Lead Auditor and Mining Technical Specialist for La Herradura Mine Dynamic Leaching Plant	Sonora, Mexico					
Transportation – International Cyanide Management Code Certification Audits (Initial or Recertification)							
2019	Lead Auditor and Transportation Technical Specialist for CyPlus Idesa Mexico Supply Chain	Mexico					
·	Other Audits						
2012	Lead Auditor for Legal Compliance Environmental Audit at Thompson Creek Mine	Idaho, USA					
2018	Lead Auditor for Legal Compliance Water Environmental Audits at Five Mining, Smelting, and Refining Sites for Confidential Client	Arizona and Texas, USA					

Cyanide-related Operations Experience

Each auditor must have at least 3 years; at least one auditor must have at least 7 years' experience.

Auditor	Yrs.	Relevant Position Titles	Types of Operations
Kent R. Johnejack	24+	Registered Professional Engineer (Civil); Senior Engineer/Principal; and Certified Environmental Auditor	Since 1995, Kent has worked in the mining industry, and associated transportation and production activities, as a consulting engineer. He has been involved with groundwater and surface water permitting, closure, remediation, spill cleanup, due diligence, waste characterization, sampling and analysis, civil design, construction oversight, regulatory compliance inspections, and auditing. Prior to 1995, Kent worked in land development, infrastructure, and low-level radioactive waste projects.





Statement of No Conflict

I certify that I have not audited any component of this facility for which I was responsible for design or development; nor have I within the past year been an employee of the facility, its parent company, or associated affiliates. Excluding audits, I have not derived more than 30% of my income within the past 5 years from the facility, its parent, or associated affiliates. I have not participated in more than three consecutive Cyanide Code audits of this facility. I have participated in at least three health, safety, and/or environmental audits in the past 7 years and am familiar with standard audit procedures as well as with the protocols developed by the International Cyanide Management Institute for implementation of the Code.

Signed	Name	Signature	Date
Lead Auditor* and Transportation Technical Specialist	Kent Johnejack	Kithhue	September 10, 2019

Use additional pages if necessary

State of Arizona

County of The

Subscribed and sworn (or affirmed) before me this

day September, 20/9

by Kent Johnelack,

Notary Public

^{*}The lead auditor's signature must be certified by notarization or equivalent.