Auditor Credentials Form

Facility Audited: MINERA YANAQUIHUA, S.A.C. Arequipa, Perú

Date: March 16-18th, 2014 & July 24-25th, 2015

Lead Auditor Credentials

Lead Auditor: Jorge Efrén Chong Pérez

Auditor Certification Number: AA-012-2010 Updated July 17th, 2015

Certifying Organization:

Name: Ministerio de Ambiente de Panamá (MiAmbiente)

Telephone Number: +507-500-0837

Address: Edificio # 804 Albrook, Balboa - Ancón, Ciudad de Panamá.

Web Site Address: http://www.miambiente.gob.pa/

Minimum experience: 3 audits in past 7 years as Lead Auditor

Minimum experience: 3 audits in past 7 years as Lead Auditor							
Year	Type of Facility, Type of Audit Led	Country & State/Province					
2015	Cyanide Mining – (Lead Auditor following ICMI protocol)	Dominican Republic / Cotuí					
	Cyanide Transportation - (Lead Auditor following ICMI	Honduras					
2014	protocol)	San Pedro Sula, Cortés					
	Cyanide Transportation – (Lead Auditor following ICMI)						
2014	protocol)	Dominican Republic / S.D.					
2014	Cyanide Mining – (Lead Auditor following ICMI protocol)	Perú / Arequipa					
	Cyanide Production – (cyanide warehouse audit following						
2013	ICMI protocol)	Perú / Lima					
2013	Cyanide Transportation - (following ICMI protocol)	Perú / Lima					
2013	Cyanide Transportation - (following ICMI protocol)	Perú / Lima					
2013	Cyanide Transportation - (following ICMI protocol)	Perú / Lima					
2013	Gold Mine Gap Analysis – (ESH Compliance)	Perú / Arequipa					
	Cyanide Consignor / Interim Storage - (following ICMI						
2013	protocol)	Perú / Lima					
2013	Cyanide Transportation - (following ICMI protocol)	Perú / Arequipa					
2013	Cyanide Transportation - (following ICMI protocol)	Perú / Lima					
2013	Cyanide Transportation - (following ICMI protocol)	Perú / Lima					
2013	Cyanide Transportation - (following ICMI protocol)	Perú / Lima					
2012	Nonmetallic mine audit. Environmental Compliance audit	Panamá /Chiriquí					
2009	Tunneling (TBM) Project (ESH Compliance audit)	Panamá / Chiriquí					
2009	Hydro electrical project (ESH Compliance audit)	Panamá / Chiriquí					
2009	hydro electrical project (ESH Compliance audit)	Panamá / Chiriquí					

Cyanide-related Operations Experience

Each auditor must have at least 3 years; at least one auditor must have at least 7 year experience

Aud	itor Yrs.	Relevant Position Titles	Types of Operations
Jorge	Chong 4	Government Mine Inspector	Gold Mining Operation
Jorge	Chong 5	Mine ESH Supervisor	Gold Mining Operation

Statement of No Conflict

MMA, R

I certify that I have not audited any component of this facility for which I was responsible for design or development; nor have I within the past year been an employee of the facility, its parents company, or associated affiliates. Excluding audits, I have not derived more than 30% of my income within the past 5 years from the facility, its parent, or associated affiliates. I have not participated in more than two consecutive Cyanide Code audits of this facility. I have participated in at least 3 health, safety, and/or environmental audits in the past 7 years and am familiar with standard audit procedures as well as with the protocols developed by the International Cyanide Management Institute for implementation of the Code.

Signed	Name	Signature	Date
Lead Auditor *	Jorge Chong	In Chi Chy Cary	March 4 ⁺⁶ , 16

*The lead auditor's signature must be certified by notarization or equivalent

Yo DR ALDOR SAENZ, Notario Segundo del Circuito de Calún, con cédide de del Circuito de Calún, con cédide de del Circuito de Calún, con cédide de

Que dada la centeza de la lidentidad de (los) sujeto(s) que firmó (firmaron) el

presente decumento o (s. firma(s) estació) autémica(s)

DR. ALDO R. SAENZ NOTARIO PUBLICO SEGUNDO estigo